

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2401871

INV Date : 16-12-2024

Reference CS3/SMR24120138/Enh3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SML 1923M
Insured Veh. SG 6011S
Claim No. BUS/12/24/5005
Policy No.
Accident Date 04/12/2024
Inspection Date 11/12/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		Ref:	CS3/SMR24120138/Enh3e2	
		Date:	16/12/2024	
		Code:	SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SG 6011S	Veh. Inspected	SML 1923M	
Policy No.	-	Coverage	0	
Claim No.	BUS/12/24/5005	Excess	\$0.00	
Assign From	HUA YEN	Assign Date	10/12/2024	
2. Vehicle Details				
Make & Model	HYUNDAI AD AVANTE	C.C	1591	
Engine No.	G4FGKU147176	Year of Reg.	09/05/2019	
Chassis No.	KMHD841CMKU910864	Colour	GREY	
Odometer	129117 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	195/65 R15	MICHELIN	5	
L/H Front Tyre	195/65 R15	MICHELIN	5	
R/H Rear Tyre	195/65 R15	MICHELIN	5	
L/H Rear Tyre	195/65 R15	MICHELIN	5	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	04/12/2024	Inspection Date	11/12/2024 (10:45)	
Survey held at	M.S LLH 1, KAKI BUKIT AVENUE 6 #01-67 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M



PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M



PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M



PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M



PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M



PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M



PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M



PHOTOGRAPHS FOR VEHICLE NO. : SML 1923M

