

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO WD 7358D

REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	FRONT BUMPER	TO REPAIR SEE LABOUR	\$2,985.00	\$0.00	
1	HEADLAMP RH	SERVICEABLE	\$1,485.00	\$0.00	
1	SIGNAL LAMP RH	SERVICEABLE	\$859.00	\$0.00	
1	STEP PANEL HOUSING RH	SERVICEABLE	\$850.00	\$0.00	
1	STEP PANEL TOP RH	SERVICEABLE	\$335.00	\$0.00	
1	STEP PANEL CENTER RH	TO REPAIR SEE LABOUR	\$335.00	\$0.00	
1	STEP PANEL BOTTOM RH	TO REPAIR SEE LABOUR	\$335.00	\$0.00	
1	STEP PANEL LOWER SUPPORT RH	TO REPAIR SEE LABOUR	\$1,650.00	\$0.00	
	LESS 10.00% DISCOUNT		(\$883.40)	\$0.00	
			\$7,950.60	\$0.00	
	Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
Qty 1	Description of Parts FRONT BUMPER OUTER NET / COVER (SN)	Condition DENTED	Workshop Estimate (\$) \$522.00	Our Adjusted (\$) \$200.00	
	•				
	•	DENTED	\$522.00	\$200.00	
	FRONT BUMPER OUTER NET / COVER (SN)	DENTED	\$522.00	\$200.00 \$200.00	
	FRONT BUMPER OUTER NET / COVER (SN)	DENTED	\$522.00 \$522.00	\$200.00 \$200.00	
	FRONT BUMPER OUTER NET / COVER (SN) Labo Description of Parts LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, STEP PANEL CENTER RH, STEP PANEL BOTTOM RH AND	DENTED	\$522.00 \$522.00 Workshop Estimate (\$)	\$200.00 \$200.00 Our Adjusted (\$)	
	FRONT BUMPER OUTER NET / COVER (SN) Labo Description of Parts LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, STEP PANEL CENTER RH, STEP PANEL BOTTOM RH AND STEP PANEL LOWER SUPPORT RH	DENTED	\$522.00 \$522.00 Workshop Estimate (\$) \$1,000.00	\$200.00 \$200.00 Our Adjusted (\$) \$300.00	
	PRONT BUMPER OUTER NET / COVER (SN) Labo Labo Description of Parts LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, STEP PANEL CENTER RH, STEP PANEL BOTTOM RH AND STEP PANEL LOWER SUPPORT RH TO DO ANTI RUST	DENTED Our Condition NOT NECESSARY	\$522.00 \$522.00 Workshop Estimate (\$) \$1,000.00 \$120.00	\$200.00 \$200.00 Our Adjusted (\$) \$300.00	
	FRONT BUMPER OUTER NET / COVER (SN) Labo Description of Parts LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, STEP PANEL CENTER RH, STEP PANEL BOTTOM RH AND STEP PANEL LOWER SUPPORT RH TO DO ANTI RUST TO CHECK WIRING SYSTEM	DENTED Our Condition NOT NECESSARY	\$522.00 \$522.00 Workshop Estimate (\$) \$1,000.00 \$120.00	\$200.00 \$200.00 Our Adjusted (\$) \$300.00 \$0.00	
	FRONT BUMPER OUTER NET / COVER (SN) Labo Description of Parts LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, STEP PANEL CENTER RH, STEP PANEL BOTTOM RH AND STEP PANEL LOWER SUPPORT RH TO DO ANTI RUST TO CHECK WIRING SYSTEM	DENTED Our Condition NOT NECESSARY	\$522.00 \$522.00 \$00 \$1,000.00 \$120.00 \$1,000.00	\$200.00 \$200.00 Our Adjusted (\$) \$300.00 \$0.00 \$200.00	

KSC

KENNETH KONG SENG CHEONG

Report Ref No: CS/FCI24120139/Kvh3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.