



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24120139/Kvh3e2
16 RAFFLES QUAY	Date:	16/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 564D	Veh. Inspected	WD 7358D
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24010727MFCT	Excess	\$0.00
Assign From	EILEEN WANG	Assign Date	10/12/2024

2. Vehicle Details

Make & Model	CAMC HN5311X40D9M6	C.C	11813
Engine No.	CM6D2840060123J03163	Year of Reg.	04/12/2023
Chassis No.	LZ5N2DE58PB004437	Colour	WHITE / BLUE
Odometer	29247 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	315/80 R22.5 (D)	WONDERLAND	4/5
L/H Front Tyre	315/80 R22.5 (D)	WONDERLAND	4/5
R/H Rear Tyre	315/80 R22.5 (D/D)	AEOLUS	6/6/5/5
L/H Rear Tyre	315/80 R22.5 (D/D)	AEOLUS	6/6/5/5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/12/2024	Inspection Date	11/12/2024
Survey held at	SQM PTE LTD - 160 SIN MING DRIVE, SIN MING AUTOCITY #06-01, SINGAPORE 575722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days