



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: JOANNE		Ref: CS/FCI24120144/Tvh3m4(N) Date: 10/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6608C	Veh. Inspected	SMD 329C
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010777MFCT	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	10/12/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTEKB3GH30J002394	Colour	WHITE
Odometer	98886 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55R18	YOKOHAMA	6 mm
L/H Front Tyre	235/55R18	YOKOHAMA	6 mm
R/H Rear Tyre	235/55R18	YOKOHAMA	6 mm
L/H Rear Tyre	235/55R18	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/12/2024	Inspection Date	23/12/2024
Survey held at	48 TOH GUAN ROAD EAST #02- 146 ENT HUB (S) 608586		
Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	