

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120147/AUA3Q2**Date:** 28/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070179422
Claimant Vehicle No : YQ9838E **Insured Vehicle No :** YP971S
 Date of Loss: 06/12/2024 Nature of Claim: TP Claim No: 7892491230SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ9838E**
 Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (M) Engine No: 4P10F69338
 Reg. Date: 30/03/2023 (Man. Year: 2022) Chassis No: FEB21EA36154
 Colour: White Odometer: 48266 km
 Engine Capacity: 2998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,938.50	3,750.00	4,188.50	52.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,280.00	1,180.00	47.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,398.50	5,030.00	5,368.50	51.63
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,398.50	4,000.00	6,398.50	61.53
+ Loss of Use (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,627.25		

INSPECTION

Date of Assignment: 06/01/2025
 Date Inspected: 06/01/2025 Inspected At: SM INTEGRATED PTE LTD (HQ)
 1 Kaki Bukit Ave 6., Blk C #01-43 Autobay
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	798.00 FL	*- FL
2	1		*FRONT BUMPER SIDE GUIDE RH	Not Necessary	189.00 FL	*- FL
3	1		*RH FRONT BUMPER BRACKET	Not Necessary	254.00 FL	*- FL
4	1		*RH FRONT HEADLAMP	Cracked	659.00 FL	*659.00 FL
5	1		*RH FRONT SIDE LAMP	Cracked	326.00 FL	*326.00 FL
6	1		*RH FRONT SIGNAL LAMP	Cracked	284.00 FL	*284.00 FL
7	1		*RH FRONT HEADLAMP LOWER RUBBER	Not Necessary	38.00 FL	*- FL
8	1		*RH FRONT CORNER PANEL	Dented	689.00 FL	*459.00 FL
9	1		*RH FRONT CORNER PANEL INNER RUBBER	Not Necessary	36.00 FL	*- FL
10	1		*FRONT GRILLE	Cut	1,187.00 FL	*1,187.00 FL
11	1		*FRONT GRILLE EMBLEM FUSO	Necessary	157.00 FL	*157.00 FL
12	1		*FRONT PANEL	Dented	1,451.00 FL	*1,451.00 FL
13	1		*FRONT WIPER GARNISH	Cracked	477.00 FL	*477.00 FL
14	1		*RH FRONT STEP PANEL	Not Necessary	659.00 FL	*- FL
15	1		*RH FRONT STEP PANEL GARNISH	Not Necessary	589.00 FL	*- FL
16	1		*RH FRONT ROUND MIRROR	Not Necessary	197.00 FL	*- FL
17	1		*RH FRONT SQUARE MIRROR	Not Necessary	215.00 FL	*- FL
18	1		*RH FRONT MIRROR ARM	Not Necessary	408.00 FL	*- FL
19	1		*RH FRONT MIRROR ARM COVER	Not Necessary	152.00 FL	*- FL
20	1		*LH FRONT HEADLAMP CLIPS	Not Necessary	18.00 FS	*- FS
21	4		*LH FRONT CORNER RUBBER CLIPS	Not Necessary	12.00 FS	*- FS
22	1		*LH FRONT HEADLAMP LOWER RUBBER CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,815.00	5,000.00
- List Item Discount on L Items 10.00/25.00% (\$\$)	876.50	1,250.00
Total Parts (\$\$)	7,938.50	3,750.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	1,200.00	600.00
2	LABOUR FOR SPRAY PAINTING	New	1,000.00	650.00
3	WIRING CHECK	New	60.00	30.00
4	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	200.00	0.00
Gross Labour Cost (\$\$)			2,460.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >