

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 3160X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	STAND PANEL -LH	TO REPAIR SEE LABOUR	1,914.29	-
1	STEP PANEL -LH	TO REPAIR SEE LABOUR	594.41	-
1	STEP PANEL LOWER -LH	NOT NECESSARY	253.79	-
1	STEP PANEL UNDER COVER -LH	NOT NECESSARY	189.18	-
1	STEP ALLOY MAT TOP -LH	NOT NECESSARY	520.63	-
1	STEP ALLOY MAT LOWER -LH	NOT NECESSARY	393.40	-
1	STEP PANEL REFLECTOR -LH	NOT NECESSARY	233.53	-
1	FRONT DOOR ASSY -LH	DENTED	8,832.24	4,501.32
1	FRONT DOOR HINGE UPPER -LH	NOT NECESSARY	227.77	-
1	FRONT DOOR HINGE LOWER -LH	NOT NECESSARY	227.77	-
1	FRONT DOOR PILLAR -LH	NOT NECESSARY	3,106.53	-
1	FRONT DOOR INNER PILLAR -LH	NOT NECESSARY	2,346.88	-
1	FRONT DOOR INNER GARNISH -LH	NOT NECESSARY	336.86	-
1	FRONT DOOR FRAME RUBBER SEAL -LH	NOT NECESSARY	549.26	-
1	FRONT DOOR LAMP -LH	NOT NECESSARY	361.81	-
1	REAR CORNER PANEL HANDLE -LH	NOT NECESSARY	837.55	-
	LESS 25% DISCOUNT		-5,231.48	-1,125.33
			15,694.42	3,375.99
	LABOUR			
	LABOUR TO REMOVE & REFIT FRONT DOOR & REALIGNMENT & TRANSFER PARTS. }		100.00	200.00
	LABOUR TO REMOVE & REFIT DOOR LAMP & CONNECT WIRE. }		180.00	-
	LABOUR TO KNOCK & RENEW & WELD & REFIT ALL AFFECTED AREA. INCLUSIVE OF THE REPAIR OF STAND PANEL -LH AND STEP PANEL -LH. }		950.00	-
	TO RUST PROOFING AT ACCIDENT AFFECTED AREA.	NOT NECESSARY	400.00	-
	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA.		850.00	300.00
			2,480.00	500.00
	GRAND TOTAL		18,174.42	3,875.99

Report Ref No. CS/LIP24120151/Uvh3m4(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LIP24120151/Uvh3m4(N)

MARKET VALUE: \$68,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$13,610.00=NETT VALUE: \$54,390.00

CHUA KANG SENG

**Licensed Appraiser**