

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24120152/TPA3Q2**Date:** 07/04/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0003653
Claimant Vehicle No : SDG1414Z **Insured Vehicle No :** GBH6186S
 Date of Loss: 07/12/2024 Nature of Claim: TP Claim No: MFL2024D0014720

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDG1414Z**
 Make & Model: VOLKSWAGEN GOLF R, 2.0 (A) Engine No: CJX144081
 Reg. Date: 24/02/2017 (Man. Year: 2016) Chassis No: WVWZZZAUZHW120792
 Colour: Grey Odometer: 111981 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18 Rear Tyre Size: 235/40 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,221.63	3,690.42	1,531.21	29.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	3,838.00	3,482.00	47.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,541.63	7,528.42	5,013.21	39.97
+ GST 9.00/9.00% (S\$)	1,128.75	677.56	451.19	39.97
Nett Amount (S\$)	13,670.38	8,205.98	5,464.40	39.97
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		8,808.16		

INSPECTION

Date of Assignment: 13/12/2024
 Date Inspected: 13/12/2024 Inspected At: Volkswagen Group Singapore Pte Ltd (HQ)
 247 ALEXANDRA ROAD
 Singapore 159934
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2025)
Parts:	143	VOLKSWAGEN GOLF R 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDG1414Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Bent	2,030.18 FS	*1,827.16 FS
2	1		*COVER FOR BUMPER PRIMED	Deformed	1,681.58 FS	*1,513.42 FS
3	1		*SENSOR BRACKET	Necessary	32.24 FS	*29.02 FS
4	1		*SENSOR BRACKET (2 PCS)	Necessary	64.48 FS	*58.03 FS
5	1		*SENSOR BRACKET	Necessary	32.24 FS	*29.02 FS
6	1		*SEAL RING SATIN BLACK (4 PCS)	Necessary	6.52 FS	*5.87 FS
7	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	50.43 FS	*- FS
8	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	50.43 FS	*- FS
9	1		*GUIDE BUMPER CTR BRACKET	Not Necessary	172.32 FS	*- FS
10	1		*2K-PLASTIC ADHESIVE	Necessary	94.98 FS	*85.48 FS
11	1		*BONDING AGENT FOR PLASTIC	Necessary	78.24 FS	*70.42 FS
12	1		*FOAM INSERT	Not Necessary	100.10 FS	*- FS
13	1		*RADIATOR GRILLE SATIN BLA	Not Necessary	747.89 FS	*- FS
14	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*72.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,221.63	3,690.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	3,360.00	1,596.00
2	SPRAY PAINT	New	3,200.00	1,520.00
3	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	266.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	456.00
Gross Labour Cost (\$\$)			7,320.00	3,838.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >