



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 5062P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
4	HOSE CLAMP;CHARGE AIR PIPE/N	NECESSARY	60.60	60.60
1	FAN COVER;FAN/N	CRACKED	76.63	76.63
1	CHARGE AIR COOLER. XR ^/R	BENT	659.50	659.50
1	HYDRAULIC HOSE;OIL COOLER./N	PUNCTURE	41.53	41.53
1	HOSE;SILENCER;COMPR MTG/N	PUNCTURE	33.97	33.97
2	HOSE;CHARGE AIR COOLER/N	PUNCTURE	342.88	342.88
1	VERTICAL PILLAR @ KL+KR;SIDE FRAME/N	DENTED	228.60	228.60
1	PRESSURE SWITCH;AIR INTAKE/N	NECESSARY	91.05	91.05
1	CHARGE AIR PIPE;CHARGE AIR COOLER/N	DENTED	378.15	378.15
1	HYDRAULIC OIL TANK;FLUID RESVR./N	CRACKED	309.46	309.46
1	AIR CLEANER ASSY/N	CRACKED	158.72	158.72
1	INTAKE MANIFOLD;AIR PIPE;ENG/N	BENT	534.99	534.99
1	REVERSE BUZZER;24V;97DBA/N	NECESSARY	12.00	12.00
4	VIBRATION INSULATOR.RADIATOR.SUPPN/N	NECESSARY	95.36	95.36
1	HOSE;OIL COOLER;TUBE;K/N	PUNCTURE	35.98	35.98
2	PVC HOSE 2;AIR CLEANER BX ASSY/N	NECESSARY	77.14	77.14
20	SIKAFLEX 255 EXTRA BLACK (400 ML/SAU)	NECESSARY	240.00	240.00
1	V-CLAMP;CHARGE AIR COOLER/N	NECESSARY	28.18	28.18
1	RADIATOR GRILL JL-KL;SIDE PANEL ASSY/N	CRACKED	612.00	612.00
1	COMPARTMENT HINGE RHS 1@ JL/N	DISTORTED	122.10	122.10
1	BUMPER.REAR.F/G.C&D SERIES/N	BENT	305.00	305.00
2	GAS JACK 0400N;RR ENG DOOR/N	NECESSARY	52.00	52.00
1	ENGINE REAR VENT COVER/N	DENTED	65.00	65.00
2	HOSE CLAMP;TUBES;RAD/N	NECESSARY	4.74	4.74
1	VALVE.AIR INTAKE.AIR CLEANER/N	DENTED	33.26	33.26
2	INSULATION HOLDER 06;1.0MM ALUM SHEET/N	NECESSARY	48.84	48.84
1	ALUM WIRE MESH;ENG DR;1PC=1.8M/N	DENTED	172.60	172.60
1	EDS HANOVER;REAR SIGN;17X32/N	BENT	459.00	459.00
2	REFLEX REFLECTOR/N	CRACKED	2.70	2.70
1	LED TAIL/STOP LAMP/N	CRACKED	97.20	97.20
1	LED REVERSE LAMP/N	CRACKED	105.60	105.60

Report Ref No. CS/FCI24120155/Knh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LED INDICATOR LAMP/N	CRACKED	204.38	204.38
2	GAS JACK 0400N;RR ENG DOOR/N	NECESSARY	52.00	52.00
2	LED LICENSE PLATE LAMP/N	NECESSARY	42.80	42.80
1	COVER PLATE;LH;NOISE SHIELD;ENG COMPT/N	DENTED	139.18	139.18
4	LATCH HOOK;FRT GRILLE PANEL;CL/N	DISTORTED	23.20	23.20
1	MOUNTING BRKT;5MM STEEL;RR FRAME/N	PUNCTURE	34.40	34.40
1	REAR WINDSCREEN..SN C&D/N	BROKEN	170.00	170.00
1	DOOR FRAME;ENG COMPARTMENT DR;ALUM/N	BENT	369.00	369.00
1	REAR DOOR;F/GLASS;C & C+ SERIES/N	BROKEN	523.00	523.00
1	DOOR FRAME JL-KL;RAD.GRILL/N	BENT	321.42	321.42
1	ATTACHMENT BRACKET BOTTOM;RR FRAME/N	DISTORTED	57.14	57.14
1	INSULATION 01;CPSS25;25MMX1MX2M;WIRING/N	NECESSARY	149.13	149.13
1	COMPARTMENT HINGE LHS 1@ HL/N	DISTORTED	122.10	122.10
1	INSULATION HOLDER 01;1.0MM ALUM SHEET/N	NECESSARY	33.42	33.42
4	INSULATION HOLDER 04;1.0MM ALUM SHEET/N	NECESSARY	77.12	77.12
2	INSULATION HOLDER 03;1.0MM ALUM SHEET/N	NECESSARY	74.20	74.20
1	CABLE HARNESS;ENG MGMT SYS/N	DENTED	95.65	95.65
1	PIPE ASSEMBLY.HYDRAULIC PUMP/N	BENT	1,228.10	1,228.10
1	CHARGE AIR PIPE;CHARGE AIR COOLER/N	DENTED	435.41	435.41
1	FRAME;RADIATOR;SUSPN/N	BENT	891.07	891.07
2	HOSE CLAMP.INTAKE MANIFOLD.AIR PIPE/N	NECESSARY	2.20	2.20
2	PILLAR REPAIR KIT/N	BENT	1,256.90	1,256.90
1	REAR DOME;F/GLASS;SN SERIES C/N	BENT	1,200.00	1,200.00
1	REAR FRAME PILLAR;RR FRAME/N	DISTORTED	153.00	153.00
1	ATTACHMENT BRACKET MID;RR FRAME/N	BENT	162.00	162.00
4	ENGINE REAR VENT COVER BRACKET/N	DENTED	145.60	145.60
1	VANITY PANEL @ EL;EXIT DR/N	BENT	75.00	75.00
1	HOSE;PIPES & HOSES/N	PUNCTURE	12.51	12.51
1	MASS FLOW SENSOR;ENG MGMT SYS/N	DENTED	242.17	242.17
1	UNION ASSY;AIR INTAKE/N	NECESSARY	14.54	14.54
1	HOSE;HYDRAULIC PUMP./N	NECESSARY	13.29	13.29
1	CLIP.PVC HOSE SIZE 9/N	NECESSARY	4.50	4.50
1	GASKET;CABLE HARNESS;EMS INJ SYS/N	NECESSARY	2.31	2.31

Report Ref No. CS/FCI24120155/Knh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
20	PLASTIC TUBE;OD6;A/C/S./N	NECESSARY	61.20	61.20
1	INSERT CONNECTION;AIR DRYER/N	NECESSARY	10.13	10.13
8	STRIP;RADIATOR./N	NECESSARY	79.68	79.68
5	HOSE CLAMP;23-35MM;OIL COOLER/N	NECESSARY	9.85	9.85
1	ELBOW UNION;8M10X1K;TURBO CHARGER/N	NECESSARY	10.99	10.99
1	FRAME;EXPN-TANK W/CONN/N	NECESSARY	79.39	79.39
1	RADIATOR ASSY. SCANIA EU4 & 5 XR ^/N	BENT	831.46	831.46
1	VALVE.RELAY.PARKING VALVE/N	DENTED	116.96	116.96
1	HAND CONTROL UNIT;PARKING BRAKE VALVE/N	DENTED	310.28	310.28
1	LEVEL PIPE ASSY.LEVEL GLASS/N	DENTED	31.02	31.02
1	CLIP;ADJUSTABLE STRG COLUMN./N	NECESSARY	2.18	2.18
1	SLEEVE;CABLE HARNESS;EMS INJ SYS/IN	NECESSARY	11.54	11.54
			15,366.20	15,366.20
	<u>LABOUR</u>			
	WORKSHOP LABOUR.		188.00	188.00
	CONTRACTOR'S REPAIR CHARGES.		7,680.00	7,680.00
	TOWING CHARGES.	NOT NECESSARY	158.00	-
			8,026.00	7,868.00
GRAND TOTAL			23,392.20	23,234.20
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				23,234.20

Report Ref No. CS/FCI24120155/Knh3m4(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.