

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24120169/KNH3E2**Date:** 23/12/2024**REFERENCE**

Insured/Claimant:	GOH HWEE NGEE MICHELLE	Policy No:	MPC24A00323001	
Date of Loss:	05/12/2024	Nature of Claim:	OD	Claim No: DMPC2401694H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDP14D		Engine No:	G4FGGU169394
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)		Chassis No:	KMHD841CMHU161219
Reg. Date:	16/08/2016 (Man. Year: 2016)		Odometer:	70818 km
Colour:	Black			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	S\$21,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,001.00	539.00	462.00	46.15
Miscellaneous Items	100.00	50.00	50.00	50.00
Labour	1,820.00	410.00	1,410.00	77.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,921.00	999.00	1,922.00	65.80
Approved Total (Overridden) (\$\$)		800.00		
(\$\$)	2,921.00	800.00	2,121.00	72.61
+ GST 9.00/9.00% (\$\$)	262.89	72.00	190.89	72.61
Nett Amount (\$\$)	3,183.89	872.00	2,311.89	72.61

INSPECTION

Date of Assignment:	12/12/2024	Present Location:	Accord Auto Services Pte Ltd (HQ)
Date Inspected:	13/12/2024	Inspected At:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2024)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDP14D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Buckled / Cracked	330.00 F	*330.00 F
2	2		*REAR BUMPER SIDE RETAINER (WCP)	Serviceable	44.00 F	*- F
3	1		*REAR BUMPER REFLECTOR LH (WCP)	Serviceable	28.00 F	*- F
4	1		*REAR BUMPER REFLECTOR RH (WCP)	Serviceable	28.00 F	*- F
5	1		*REAR BUMPER LOWER (WCP)	Serviceable	125.00 F	*- F
6	1		*REAR REINFORCEMENT BAR (WCP)	Bent	160.00 F	*160.00 F
7	1		*REAR END PANEL (WCP)	Repair	160.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH (WCP)	Serviceable	35.00 F	*- F
					Sub Total (S\$)	910.00 490.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	91.00 49.00
					Total Parts (S\$)	1,001.00 539.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR BUMPER CLIPS SET (NECESSARY)	50.00	50.00
2	1	REAR FENDER INNER SHILED RH SET (NOT NECESSARY)	50.00	0.00
Sub Total (\$\$)			100.00	50.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	800.00	200.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	200.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	10.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			1,820.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >