

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24070015/TVH3E2  
**Date:** 07/08/2024**REFERENCE**

Insured/Claimant:	DAMJANOVIC ROBERT RADA	Policy No:	7230015594
Date of Loss:	28/06/2024	Nature of Claim:	OD
		Claim No:	6138830386SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMY1959S</b>		
Make & Model:	AUDI E-TRON, SPORTBACK ADV 50 QUATTRO (A)	Engine No:	HIDDEN
Reg. Date:	16/02/2023 (Man. Year: 2022)	Chassis No:	WAUZZZGEXPB017967
Colour:	Black	Odometer:	7589 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$250,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	255/50 R20	Rear Tyre Size:	255/50 R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,569.00	3,544.64	8,024.36	69.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,052.00	6,952.00	2,100.00	23.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>20,621.00</b>	<b>10,496.64</b>	<b>10,124.36</b>	<b>49.10</b>
<b>- Excess (\$\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>20,021.00</b>	<b>9,896.64</b>	<b>10,124.36</b>	<b>50.57</b>
<b>+ GST 9.00/9.00% (\$\$)</b>	<b>1,801.89</b>	<b>890.70</b>	<b>911.19</b>	<b>50.57</b>
<b>Nett Amount (\$\$)</b>	<b>21,822.89</b>	<b>10,787.34</b>	<b>11,035.55</b>	<b>50.57</b>

**INSPECTION**

Date of Assignment:	03/07/2024		
Date Inspected:	04/07/2024	Inspected At:	281 Alexandra Road Singapore 159938 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER IMPACT PROTECTION - SELENITE SILVER	Torn	1,011.00 FS	*808.80 FS
2	2		*FRONT BUMPER SPOILER - LH / RH	Not Necessary	392.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	318.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Missing	263.00 FS	*210.40 FS
5	1		*FRONT PLASTIC FOAM STRIP	Not Necessary	151.00 FS	*- FS
6	2		*FRONT BUMPER TRIM - LH / RH	Not Necessary	146.00 FS	*- FS
7	2		*FRONT BUMPER SPOILER - LH / RH FRONT	Not Necessary	238.00 FS	*- FS
8	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	664.00 FS	*- FS
9	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	112.00 FS	*- FS
10	1		*FRONT ENGINE UNDERSHIELD	Not Necessary	801.00 FS	*- FS
11	1		*FRONT ENGINE UNDERSHIELD FIXING PARTS	Not Necessary	343.00 FS	*- FS
12	1		*FRONT AIR GUIDE - LOWER REAR	Not Necessary	85.00 FS	*- FS
13	1		*FRONT CROSS MEMBER	Not Necessary	521.00 FS	*- FS
14	2		*FRONT WHEEL ARCH COVER - LH / RH	Deformed	1,382.00 FS	*1,105.60 FS
15	1		*A/C HOSE	Not Necessary	248.00 FS	*- FS
16	1		*A/C HOSE	Not Necessary	187.00 FS	*- FS
17	1		*A/C HOSE	Not Necessary	311.00 FS	*- FS
18	1		*A/C HOSE	Not Necessary	252.00 FS	*- FS
19	1		*HEAT EXCHANGER	Not Necessary	539.00 FS	*- FS
20	1		*HEAT EXCHANGER WITH REFRIGENT RECEIVER	Not Necessary	574.00 FS	*- FS
21	2		*FRONT SIDE MEMBER - LH / RH	Not Necessary	504.00 FS	*- FS
22	1		*FRONT LOCK CARRIER	Cracked	1,443.00 FS	*1,154.40 FS
23	2		*FRONT BUMPER ADAPTOR - LH / RH	Not Necessary	114.00 FS	*- FS
24	1		*RADIATOR COOLANT (6PCS)	Necessary	332.00 FS	*265.44 FS
25	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	53.00 FS	*- FS
26	1		*RADIATOR AIR GUIDE - LOWER FRONT	Not Necessary	85.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**    **11,569.00**    **3,544.64**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS AND HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSOR, RADIATOR AND ADDITIONAL RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,800.00	1,800.00
3	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
4	TO REINSTALL FRONT BUMPER, TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,500.00	2,400.00
5	TO RESPRAY FRONT BUMPER SPOILER AND BOTH WHEEL ARCH TRIMS	New	300.00	300.00
6	TO CARRY OUT DE-ENERGENEISING HIGH VOLTAGE SYSTEM. DEACTIVATION AND ACTIVATION	New	480.00	480.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,052.00</b>	<b>6,952.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >