



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 3106B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET (WCP)	NOT NECESSARY	2,800.00	-
1	BONNET LOGO (WCP)	NOT NECESSARY	140.00	-
1	FRT GRILLE CHROME (WCP)	BROKEN	400.00	280.00
1	FRT GRILLE BACKING (WCP)	BROKEN	580.00	480.00
1	FRT GRILLE CAMERA (WCP)	NOT NECESSARY	800.00	-
1	FRT NUMBER PLATE BASE (WCP)	BROKEN	85.00	85.00
1	FRT HEADLAMP LH (WCP)	NOT NECESSARY	4,000.00	-
1	FRT HEADLAMP RH (WCP)	NOT NECESSARY	4,000.00	-
1	FRT BUMPER (WCP)	DEFORMED	1,900.00	1,900.00
1	FRT BUMPER BRACKET LH (WCP)	NOT NECESSARY	300.00	-
1	FRT BUMPER BRACKET RH (WCP)	NOT NECESSARY	300.00	-
1	FRT BUMPER INNER SPONGE (WCP)	NOT NECESSARY	200.00	-
1	FRT BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	400.00	-
1	FRT BUMPER INNER AIR GUIDE LOWER (WCP)	NOT NECESSARY	380.00	-
1	FRT BUMPER INNER AIR GUIDE UPPER (WCP)	BROKEN	350.00	125.00
1	FRT HEADLAMP LOWER BRACKET LH (WCP)	NOT NECESSARY	220.00	-
1	FRT HEADLAMP LOWER BRACKET RH (WCP)	NOT NECESSARY	220.00	-
1	FRT BUMPER CENTRE LOWER AIR GRILLE (WCP)	BROKEN	160.00	125.00
1	FRT BUMPER CENTRE LOWER AIR GUIDE LH (WCP)	NOT NECESSARY	270.00	-
1	FRT BUMPER CENTRE LOWER AIR GUIDE RH (WCP)	NOT NECESSARY	270.00	-
1	RADAR UNIT (WCP)	NOT NECESSARY	3,200.00	-
1	FRONT BUMPER CENTRE TRIM (WCP) (ADDITIONAL)	CRUSHED	400.00	400.00
	COST PLUS 10%		2,137.50	339.50
			23,512.50	3,734.50
<u>SPECIAL NETT ITEMS</u>				
1	FRT NUMBER PLATE (SN)	BENT	40.00	40.00
1	SET FRT BUMPER SENSOR (SN)	NOT NECESSARY	1,000.00	-
			1,040.00	40.00

Report Ref No. CS/GAI24120179/Eqh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		200.00	100.00
	TO PROGRAMMING & CODING FOR RADAR UNIT.	NOT NECESSARY	580.00	-
	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		1,000.00	250.00
	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE.		700.00	220.00
			2,480.00	570.00
	GRAND TOTAL		27,032.50	4,344.50
RECOMMENDED COST OF REPAIRS				4,344.50
LESS EXCESS				-700.00
NETT LIABILITY				3,644.50

Report Ref No. CS/GAI24120179/Eqh3e2(N)

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.