

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24120183/UVH3E2
Date: 11/03/2025REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBM7340E	Insured Vehicle No :	GBE2567T
Date of Loss:	12/11/2024	Nature of Claim:	TP
		Claim No:	DMCF2400109H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBM7340E	Engine No:	HIDDEN
Make & Model:	OPEL COMBO-E, (A)	Chassis No:	W0VEAZKXZPJ543396
Reg. Date:	28/10/2024 (Man. Year: 2023)	Odometer:	2877 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,593.00	1,593.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	480.00	720.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,793.00	2,073.00	720.00	25.78
+ GST 9.00/9.00% (S\$)	251.37	186.57	64.80	25.78
Nett Amount (S\$)	3,044.37	2,259.57	784.80	25.78

INSPECTION

Date of Assignment:	12/12/2024		
Date Inspected:	03/01/2025	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Mar 2025)	
Parts:	N/A	OPEL COMBO-E (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBM7340E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	900.00 FL	*900.00 FL
2	1		*REAR BUMPER PARKING SENSOR LH CENTER	Damaged	190.00 FL	*190.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	680.00 FL	*680.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	1,770.00 1,770.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	177.00 177.00
					Total Parts (S\$)	1,593.00 1,593.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPROGRAMMING REVERSE SENSOR	New	300.00	30.00
2	TO RESPRAY AFFECTED AREAS	New	450.00	250.00
3	TO RENEW DAMAGED PARTS, STRAIGHTHENED, REPAIR REAR END PANEL AND ALIGNED ALL PARTS	New	450.00	200.00
Gross Labour Cost (\$\$)			1,200.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >