10/8/24, 3:53 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24070016/ANH3E2

**Date:** 08/10/2024

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30003109806

Claimant Vehicle

No: SKS8653H Insured Vehicle No: SLV3250S

Date of Loss: 25/06/2024 Nature of Claim: TP Claim No: 364675

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKS8653H

 Make & Model:
 MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A)
 Engine No:
 27091030626168

 Reg. Date:
 13/05/2015 (Man. Year: 2015)
 Chassis No:
 WDD1173422N196545

Colour: White Odometer: 142514 km

Engine Capacity: 1595 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,782.40	1,953.50	1,828.90	48.35
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,400.00	400.00	1,000.00	71.43
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,182.40	2,353.50	2,828.90	54.59
	Approved Total (Overridden) (S\$)		1,850.00		
	(S\$)	5,182.40	1,850.00	3,332.40	64.30
	+ GST 9.00/9.00% (S\$)	466.42	166.50	299.92	64.30
	Nett Amount (S\$)	5,648.82	2,016.50	3,632.32	64.30

**INSPECTION** 

Date of Assignment: 01/07/2024

Success United Pte Ltd (HQ)

Date Inspected: 02/07/2024 Inspected At: 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/8/24, 3:53 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2024)

Parts: 143 MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKS8653H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

	*REAR BUMPER ASSY *REAR LOWER BUMPER *REAR BUMPER CHROME TRIM ASSY *REAR BUMPER BRACKET L/R	Deformed Cut Not Necessary	1,630.00 FL 485.00 FL 590.00 FL	*1,630.00 FL *485.00 FL *- FL
	*REAR BUMPER CHROME TRIM ASSY	Not Necessary		
		· ·	590.00 FL	*-FL
	*REAR BUMPER BRACKET L/R	AL CAL		
		Not Necessary	316.00 FL	*- FL
	*REAR BUMPER REINFORCEMENT	Not Necessary	780.00 FL	*- FL
	*REAR PDC PARKING SENSOR	Not Necessary	235.00 FL	*- FL
	*REAR BUMPER CLIPS	Necessary	150.00 FS	*50.00 FS
e part. S=SpcNe	ett. L=ListItemDisc.	_		
		Sub Total (S\$)	4,186.00	2,165.00
- List Item Discount on L Items 10.00/10.00% (S\$)		403.60	211.50	
		Total Parts (S\$)	3,782.40	1,953.50
9	part. S=SpcNe	*REAR BUMPER CLIPS part. S=SpcNett. L=ListItemDisc.	*REAR BUMPER CLIPS part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	*REAR BUMPER CLIPS part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)  4,186.00 403.60

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PUTTY AND RESPRAY PAINTING ON REAR BUMPER AND REAR BOOT LID	New	800.00	200.00
2	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	600.00	200.00
	Gross Labour Cost (S\$)		1,400.00	400.00
	Report was unsubmitted during this pri	nt-out.		

< END OF ESTIMATES >