

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120189/KPA3Q2**Date:** 15/01/2026**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100459100
Claimant Vehicle No : SMA1798R **Insured Vehicle No :** SGY9590P
 Date of Loss: 10/12/2024 Nature of Claim: TP Claim No: 6406291938SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA1798R**
 Make & Model: NISSAN SYLPHY, 1.6 CVT (A) Engine No: HR16926383C
 Reg. Date: 30/05/2018 (Man. Year: 2018) Chassis No: MNTBBAB17Z0032027
 Colour: Metallic Blue Odometer: 118777 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,308.20	1,164.15	4,144.05	78.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,320.00	1,680.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,308.20	2,484.15	5,824.05	70.10
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	8,308.20	2,000.00	6,308.20	75.93
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,300.00		

INSPECTION

Date of Assignment: 16/12/2024
 Date Inspected: 16/12/2024 Inspected At: Tropical Tech Automobile Services (HQ)
 INDUSTRIAL PARK 2
 Singapore 569535
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Repair	1,346.00 FL	*- FL
2	1		*REAR BOOT EMBLEM	Necessary	97.00 FL	*88.80 FL
3	1		*REAR BOOT SYLPHY DESIGNATION	Necessary	194.00 FL	*96.20 FL
4	1		*REAR END PANEL	Repair	1,239.00 FL	*- FL
5	1		*REAR BUMPER	Cracked	1,346.00 FL	*801.20 FL
6	1		*REAR BUMPER PARKING SENSOR KIT (ORIGINAL)	Serviceable	531.00 FL	*- FL
7	1		*REAR BUMPER SPONGE (SIDE)	N/S Cracked	426.00 FL	*202.30 FL
8	1		*REAR BUMPER SPONGE (CENTRE)	Serviceable	213.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER (LH)	Serviceable	124.00 FL	*- FL
10	1		*REAR BUMPER BRACKET (METAL LH SIDE)	Bent	160.00 FL	*105.00 FL
11	1		*REAR TAIL PIPE CHROME RING (LH)	Serviceable	222.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,898.00	1,293.50
- List Item Discount on L Items 10.00/10.00% (\$)	589.80	129.35
Total Parts (\$)	5,308.20	1,164.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND TRANSFER REAR BOOT NECESSARY SPART PART ITEMS }	New	1,500.00	500.00
2	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
3	REMOVE AND REFIT REAR BOOT ,REAR BOOT EMBLEM ,REAR BOOT SYLPHY DESIGNATION ,REAR BUMPER ,REAR BUMPER PARKING SENSOR KIT ,REAR BUMPER SPONGE (SIDE) ,REAR BUMPER SPONGE (CENTRE ,REAR BUMPER SIDE RETAINER (LH) ,REAR BUMPER BRACKET (METAL LH SIDE) REAR TAIL PIPE CHROME RING (LH) }	New	0.00	0.00
4	HEAT /WELD/ CUT/RENEW REAR END PANEL ,HEAT /WELD/BEATING/PULL/STRAIGHTEN /ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	0.00	0.00
5	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNRESS	New	100.00	20.00
6	UNDER COATING ON REAR DAMAED PORTION	New	200.00	0.00
7	PUTTY /PRIMER APPLICATION ,SPRAY PAINTING REAR BOOT ,REAR END PANEL,REAR BUMPER ,REAR BUMPER PARKING SENSORS	New	1,200.00	800.00
Gross Labour Cost (S\$)			3,000.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >