

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24120191/TVH3E2**Date:** 08/01/2025REFERENCE

Insured/Claimant: NEUBRONNER COLIN MICHAEL

Policy No: MPC24P00462800

Date of Loss: 11/12/2024

Nature of Claim: OD

Claim No: DMPC2401713H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMN1360B**

Make & Model: LEXUS ES250, 2.5 (A)

Engine No: A25A5172534

Reg. Date: 15/07/2019 (Man. Year: 2019)

Chassis No: JTHB11B1402010082

Colour: Silver

Odometer: 58964 km

Engine Capacity: 2487 cc

Market Value/New Car Price: S\$115,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18

Rear Tyre Size: 235/45 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,660.39	10,177.79	8,482.60	45.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,016.00	2,634.80	3,381.20	56.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,676.39	12,812.59	11,863.80	48.08
+ GST 9.00/9.00% (S\$)	2,220.88	1,153.13	1,067.75	48.08
Nett Amount (S\$)	26,897.27	13,965.72	12,931.55	48.08

INSPECTION

Date of Assignment: 12/12/2024 Present Location: Borneo Motors (S) Pte Ltd (Leng Kee)

Date Inspected: 13/12/2024 Inspected At: Borneo Motors (S) Pte Ltd

Estimated Period of Repair: 3.0 days

2 Pandan Crescent

Singapore 128462

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2025)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1360B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	L52618-33090	*ABSORBER FR BUMPER	Deformed	390.10 FL	*390.10 FL
2	1	L52611-33330	*ABSORBER FR BUMPER	Deformed	155.70 FL	*155.70 FL
3	1	L52148-33040	*BRACKET FR BUMPER	Distorted	697.60 FL	*697.60 FL
4	1	L52021-33240	*REINFORCEMENT	Not Necessary	1,400.20 FL	*- FL
5	1	L52146-33110	*BRACKET FR BUMPER	Deformed	10.50 FL	*10.50 FL
6	6	T53879-33030	*RETAINER FR FENDER	Distorted	102.00 FL	*102.00 FL
7	2	T90189-06237	*GROMMET SCREW	Necessary	5.20 FL	*5.20 FL
8	1	L52119-3T943	*COVER FR BUMPER	Torn	1,601.80 FL	*1,601.80 FL
9	1	L52542-33010	*SEAL FR BUMPER CTR	Cut	128.10 FL	*128.10 FL
10	1	L53114-33050	*GRILLE RADIATOR	Cracked	278.60 FL	*278.60 FL
11	1	L52116-33100	*SUPPORT FR BUMPER	Not Necessary	65.90 FL	*- FL
12	1	L52115-33110	*SUPPORT FR BUMPER	Distorted	65.90 FL	*65.90 FL
13	1	L53106-33010	*GARNISH SUB-ASSY	Not Necessary	311.90 FL	*- FL
14	1	L53105-33010	*GARNISH SUB-ASSY	Distorted	311.90 FL	*311.90 FL
15	1	L52128-33919	*COVER FR BUMPER	Not Necessary	75.40 FL	*- FL
16	1	L52127-33905	*COVER FR BUMPER	Distorted	75.40 FL	*75.40 FL
17	1	L52114-33520	*BRACKET FR BUMPER	Not Necessary	223.70 FL	*- FL
18	1	L53101-33670	*GRILLE SUB-ASSY	Cracked	2,331.40 FL	*2,331.40 FL
19	1	L53112-33510	*GRILLE RADIATOR	Cracked	312.80 FL	*312.80 FL
20	1	L88210-33120	*SENSOR ASSY	Not Necessary	3,235.40 FL	*- FL
21	1	L53801-33230	*FENDER SUB-ASSY RH	Not Necessary	2,468.50 FL	*- FL
22	1	L53807-33010	*SHIELD SUB-ASSY	Not Necessary	731.30 FL	*- FL
23	10	T90467-07214	*CLIP	Necessary	38.00 FL	*38.00 FL
24	1	L53295-33140	*SEAL COOL AIR	Not Necessary	446.40 FL	*- FL
25	1	T53299-33020	*PLATE COOL AIR	Not Necessary	36.20 FL	*- FL
26	12	T90467-07217	*CLIP	Necessary	43.20 FL	*43.20 FL
27	1	L53141-33170	*GARNISH RADIATOR	Not Necessary	1,911.00 FL	*- FL
28	1	L81145-33F21	*UNIT HEADLAMP	Cracked	7,119.60 FL	*7,119.60 FL
29	1	L89341-33220 C4	*SENSOR ULTRASONIC	Not Necessary	503.90 FL	*- FL
30	1	L85315-33520	*JAR WASHER A	Not Necessary	303.30 FL	*- FL
31	1	L85330-33070	*MOTOR & PUMP ASSY	Not Necessary	404.90 FL	*- FL
32	1	L82114-33130	*WIRE ENGINE ROOM	Torn	231.00 FL	*231.00 FL
33	1	L52145-33110	*BRACKET FR BUMPER	Distorted	10.50 FL	*10.50 FL
34	1	L89341-33220 B4	*SENSOR ULTRASONIC	Missing	630.40 FL	*630.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	26,657.70	14,539.70
- List Item Discount on L Items 30.00/30.00% (\$\$)	7,997.31	4,361.91
Total Parts (\$\$)	18,660.39	10,177.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUNDRIES (NECESSARY)	New	100.00	50.00
2	TO CUT WELD PANELS ON ALL	New	2,304.00	768.00
3	TO SPRAY PAINT ON FRONT	New	2,448.00	652.80
4	TO REMOVE AND REPLACE RHS HEADLAMP.	New	192.00	192.00
5	TO REMOVE AND TRANSFER FRONT	New	192.00	192.00
6	TO CONDUCT ADJUSTMENT	New	192.00	192.00
7	TO RESET ECU AND REPROGRAMME	New	192.00	192.00
8	MERIMEN'S PROCESSING FEES	New	12.00	12.00
9	TO REMOVE AND REPLACE FRONT	New	384.00	384.00
Gross Labour Cost (\$\$)			6,016.00	2,634.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >