

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120192/KNH3E2
Date: 22/01/2025**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001292930
Claimant Vehicle No :	SLR3911P	Insured Vehicle No :	QA1000L
Date of Loss:	11/12/2024	Nature of Claim:	TP
		Claim No:	384592

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3911P	Engine No:	2ZR8139676
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Chassis No:	ZYX102052306
Reg. Date:	14/08/2017 (Man. Year: 2017)	Odometer:	326338 km
Colour:	Metallic Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50Z R18	Rear Tyre Size:	235/50Z R18
Front Left Side:	Blackhawk 9 mm	Rear Left Side:	Blackhawk 9 mm
Front Right Side:	Blackhawk 9 mm	Rear Right Side:	Blackhawk 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,084.80	16,399.47	6,685.33	28.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,205.00	2,190.00	2,015.00	47.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,289.80	18,589.47	8,700.33	31.88
Approved Total (Overridden) (S\$)		13,500.00		
Nett Amount (S\$)	27,289.80	13,500.00	13,789.80	50.53

INSPECTION

Date of Assignment:	13/12/2024	
Date Inspected:	16/12/2024 Inspected At:	L H Express Motor Trading (HQ) BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 Singapore 569541
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2024)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR3911P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	955.70 FL	*955.70 FL
2	1		*FRONT BONNET LOCK	Repair	355.10 FL	*- FL
3	2		*FRONT HEADLAMP	Mtg Cracked	11,303.80 FL	*11,303.80 FL
4	1		*FRONT RADIATOR SUPPORT PANEL	Repair	650.80 FL	*- FL
5	1		*FRONT GRILLE	Mtg Cracked	485.70 FL	*485.70 FL
6	1		*FRONT GRILLE PANEL	Repair	355.60 FL	*- FL
7	1		*FRONT GRILLE EMBLEM WITH COLLISION SENSOR	Dented / Cut	1,687.20 FL	*1,687.20 FL
8	2		*FRONT HEADLAMP TOP PANEL	Repair	350.20 FL	*- FL
9	1		*FRONT TOP BUMPER	Buckled	755.60 FL	*755.60 FL
10	1		*FRONT LOWER BUMPER	Dented / Cut	557.60 FL	*369.40 FL
11	1		*FRONT BUMPER REINFORCEMENT - UPPER	Bent	550.70 FL	*475.60 FL
12	1		*FRONT BUMPER SPONGE - UPPER	Cracked	165.70 FL	*165.70 FL
13	1		*FRONT BUMPER LOWER GRILLE	Serviceable	176.20 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT - LOWER	Repair	505.10 FL	*- FL
15	1		*FRONT BUMPER SPONGE - LOWER	Serviceable	155.70 FL	*- FL
16	2		*FRONT FOG LAMP GARNISH	Serviceable	75.10 FL	*- FL
17	2		*FRONT BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
18	1		*FRONT NO PLATE HOLDER	Dented	155.60 FL	*155.60 FL
19	2		*FRONT BUMPER COLLISION SENSOR	Serviceable	530.60 FL	*- FL
20	1		*AIR CON CONDENSER	Bent	1,650.70 FL	*1,650.70 FL
21	1		*RADIATOR	Punctured	1,975.30 FL	*1,975.30 FL
22	1		*REAR TAIL-GATE	Repair	1,250.70 FL	*- FL
23	1		*REAR TAIL-GATE GLASS MOULDING	Not Necessary	116.80 FL	*- FL
24	1		*REAR TAIL-GATE INNER LOCK	Repair	425.70 FL	*- FL
25	1		*REAR TAIL-GATE EMBLEM - HYBRID	Necessary	65.70 FL	*65.70 FL
26	1		*REAR TAIL-GATE EMBLEM - CH-R	Necessary	55.20 FL	*55.20 FL
27	1		*REAR BOOT RUBBER	Serviceable	205.60 FL	*- FL
28	1		*REAR END PANEL	Repair	650.70 FL	*- FL
29	1		*REAR END PANEL INNER GARNISH	Serviceable	255.60 FL	*- FL
30	1		*REAR TOP BUMPER	Buckled	755.60 FL	*755.60 FL
31	1		*REAR LOWER BUMPER	Bent / Cracked	485.60 FL	*485.60 FL
32	1		*REAR BUMPER REINFORCEMENT	Bent	497.10 FL	*371.20 FL
33	2		*REAR REVERSE SENSOR	Serviceable	858.60 FL	*- FL
34	2		*FRONT BUMPER SENSOR	Serviceable	911.20 FL	*- FL
35	1		*REAR TOW COVER	Missing	45.70 FL	*45.70 FL
36	2		*REAR BUMPER REFLECTOR GARNISH	Serviceable	251.20 FL	*- FL
37	1		*REAR RADIO ANTENNA	Serviceable	187.20 FL	*- FL
38	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	40.00 FS	*- FS
39	20		*CLIP	Necessary	40.00 FS	*40.00 FS
40	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS
41	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	30,726.40	21,839.30
				- List Item Discount on L Items 25.00/25.00% (S\$)	7,641.60	5,439.83
				Total Parts (S\$)	23,084.80	16,399.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	1,600.00	700.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,600.00	1,200.00
3	CHECK / RECONNECT WIRING	New	45.00	40.00
4	TO SPRAY ANTI-RUST ON ACCIDENT AFFECTED PORTION	New	180.00	30.00
5	REMOVE / REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	0.00
6	REMOVE / RENEW FRONT COLLISION SENSOR AND TO PROGRAME TO FACTORY SPECIFICATION	New	380.00	120.00
7	REMOVE / RENEW AIR CON CONDENSER AND TO TOP UP GAS	New	280.00	100.00
Gross Labour Cost (S\$)			4,205.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >