



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHC 8566X

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED	\$459.40	\$459.40
2	REAR BUMPER SIDE BRACKET RH / LH @\$55.80	NOT NECESSARY	\$111.60	\$0.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	\$22.00	\$22.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	\$394.80	\$0.00
2	REAR BUMPER REINFORCEMENT BRACKET LH / RH @\$138.10	NOT NECESSARY	\$276.20	\$0.00
1	BOOTLID COVER	NOT NECESSARY	\$2,549.70	\$0.00
1	BOOTLID LOCK UPPER	NOT NECESSARY	\$224.00	\$0.00
1	BOOTLID H EMBLEM	NOT NECESSARY	\$28.00	\$0.00
1	BOOTLID HYBRID	NOT NECESSARY	\$24.30	\$0.00
1	BOOTLID IONIQ	NOT NECESSARY	\$31.30	\$0.00
1	REAR BUMPER CENTRE MOULDING	DEFORMED	\$451.25	\$451.25
1	REAR BUMPER LOWER MOULDING	NOT NECESSARY	\$155.00	\$0.00
1	REAR END PANEL	NOT NECESSARY	\$532.00	\$0.00
1	REAR PANEL LOWER PANEL	NOT NECESSARY	\$208.90	\$0.00
1	REAR BUMPER FOG LAMP	NOT NECESSARY	\$201.50	\$0.00
2	NUMBER PLATE LAMP LH / RH @\$85.30	NOT NECESSARY	\$170.60	\$0.00
1	ANTENNA ASSY - SMART	NOT NECESSARY	\$40.50	\$0.00
	LESS 25.00% DISCOUNT		(\$1,470.26)	(\$233.16)
			\$4,410.79	\$699.49

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	W/SCREEN SEALANT @\$23.00 (SN)	NOT NECESSARY	\$46.00	\$0.00
1	REAR BUMPER MAT (SN)	CUT	\$50.00	\$50.00
1	REAR NUMBER PLATE/W HOLDER (SN)	CRACKED	\$55.00	\$55.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	\$180.00	\$180.00
1	BOOTLID APP LOGO STICKER (SN)	NOT NECESSARY	\$40.00	\$0.00
2	BOOTLID COMFORT LOGO / TEL NO. STICKER (SN)	NOT NECESSARY	\$60.00	\$0.00
2	REAR FENDER ADVERTISEMENT LH / RH (SN)	NOT NECESSARY	\$200.00	\$0.00
1	BOOTLID ADVERTISEMENT (SN)	NOT NECESSARY	\$100.00	\$0.00
			\$731.00	\$285.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING		\$1,200.00	\$380.00
	SPRAY PAINTING CHARGE		\$700.00	\$380.00
	CHECK WIRING		\$60.00	\$30.00
	TUFF KOTE	NOT NECESSARY	\$90.00	\$0.00
	REMOVE / REFIX REAR WINDSCREEN UPPER / LOWER	NOT NECESSARY	\$180.00	\$0.00
	REMOVE / REFIX REVERSE SENSOR		\$60.00	\$50.00
			\$2,290.00	\$840.00
GRAND TOTAL			\$7,431.79	\$1,824.49
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,450.00
Report Ref No: CS/SMO24070017/Aqh3				

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.