

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24120206/EMA3Q2
Date: 12/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MPC0006296-01
Claimant Vehicle No : SMC1969D Insured Vehicle No : SMV1921R
Date of Loss: 08/12/2024 Nature of Claim: TP Claim No: MPC2024D0014678

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC1969D
Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1420008
Reg. Date: 27/06/2018 (Man. Year: 2018) Chassis No: GK31317240
Colour: Black Odometer: 98813 km
Engine Capacity: 1317 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,447.04	18,934.84	9,512.20	33.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,390.00	3,660.00	4,730.00	56.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,837.04	22,594.84	14,242.20	38.66
Approved Total (Overridden) (S\$)		17,950.00		
Nett Amount (S\$)	36,837.04	17,950.00	18,887.04	51.27
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		19,183.18		
Global Sum Settlement (S\$)		19,000.00		

INSPECTION

Date of Assignment: 16/12/2024
Date Inspected: 16/12/2024 Inspected At: Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
Bukit
Singapore 417883
Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2025)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC1969D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	954.20 FL	*954.20 FL
2	1		*FRONT BONNET LOCK	Bent	185.90 FL	*185.90 FL
3	2		*FRONT BONNET HINGE	Bent	130.60 FL	*130.60 FL
4	1		*FRONT BONNET AIR DUCT	Crushed	101.20 FL	*101.20 FL
5	1		*FRONT GRILLE	Broken	475.20 FL	*475.20 FL
6	1		*FRONT GRILLE EMBLEM	Broken	56.30 FL	*56.30 FL
7	1		*FRONT SUPPORT PANEL	Dented	715.30 FL	*715.30 FL
8	2		*FRONT HEAD LAMP	Broken	1,896.00 FL	*1,896.00 FL
9	2		*FRONT HEAD LAMP LOWER BRACKET	Broken	363.00 FL	*120.00 FL
10	1		*FRONT BUMPER	Broken	892.00 FL	*545.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	420.00 FL	*395.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Broken	65.00 FL	*65.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Broken	189.50 FL	*189.50 FL
14	1		*FRONT BUMPER FOG LAMP CORNER	O/S Broken / N/S Not Necessary	136.40 FL	*68.20 FL
15	2		*FRONT BUMPER FOG LAMP CORNER TOP MOULDING	Broken	64.20 FL	*64.20 FL
16	1		*RADIATOR	Dented	1,450.00 FL	*1,382.00 FL
17	1		*RADIATOR FAN MOTOR	Not Necessary	483.50 FL	*- FL
18	1		*RADIATOR FAN BLADE	Not Necessary	111.20 FL	*- FL
19	1		*RADIATOR COWLING	Broken	172.20 FL	*172.20 FL
20	1		*AIRCOND CONDENSER	Dented	1,096.60 FL	*882.00 FL
21	1		*FRONT FENDER	O/S Dented / N/S Repair	1,118.40 FL	*515.00 FL
22	2		*FRONT FENDER COWLING	Not Necessary	202.40 FL	*- FL
23	1		*MANIFOLD INSTAKE	Broken	1,325.20 FL	*1,325.20 FL
24	1		*A/C COMPRESSOR	Not Necessary	1,100.00 FL	*- FL
25	1		*ALTERNATOR	Broken	1,300.00 FL	*1,300.00 FL
26	1		*ENGINE MOUNTING RH	Not Necessary	395.20 FL	*- FL
27	1		*ENGINE MOUNTING LH	Not Necessary	315.20 FL	*- FL
28	1		*ENGINE MOUNTING CENTRE	Not Necessary	265.30 FL	*- FL
29	1		*AIR CLEANER ASSY	Not Necessary	596.60 FL	*- FL
30	1		*BATTERY BRACKET	Not Necessary	165.90 FL	*- FL
31	1		*SPARE TANK	Crushed	95.00 FL	*95.00 FL
32	1		*WASHER TANK	Crushed	152.00 FL	*152.00 FL
33	1		*BATTERY TRAY	Not Necessary	70.00 FL	*- FL
34	1		*DRIVER AIRBAG	Broken	1,780.00 FL	*1,780.00 FL
35	1		*DRIVER AIRBAG CLOCKRING	Necessary	398.00 FL	*398.00 FL
36	1		*DASHBOARD HOUSING	Broken	908.00 FL	*908.00 FL
37	1		*PASSENGER AIRBAG	Broken	2,236.80 FL	*2,236.80 FL
38	1		*AIRBAG ECU	Necessary	500.00 FL	*500.00 FL
39	2		*FRONT SAFTY BELT	Jammed	1,014.00 FL	*1,014.00 FL
40	1		*REAR BOOT COVER	Dented	859.00 FL	*859.00 FL
41	1		*REAR BOOT LOCK	Bent	280.00 FL	*280.00 FL
42	1		*REAR BOOT LOCK CATCH	Not Necessary	50.00 FL	*- FL
43	1		*REAR BOOT CENTRE GARNISH	Not Necessary	160.00 FL	*- FL
44	1		*REAR BOOT CENTRE LOGO	Not Necessary	45.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*REAR BOOT ABSORBER	Not Necessary	313.40 FL	*- FL
46	1		*REAR BOOT INNER COVER BOARD	Broken	235.00 FL	*235.00 FL
47	2		*REAR BOOT SIDE TRIM	Not Necessary	330.40 FL	*- FL
48	1		*REAR BOOT CENTRE TRIM	Not Necessary	215.20 FL	*- FL
49	2		*REAR BOOT HINGE	Not Necessary	190.40 FL	*- FL
50	1		*REAR BOOT RUBBER	Crushed	106.40 FL	*106.40 FL
51	1		*REAR BOOT EMBLEM (FIT)	Necessary	35.00 FL	*35.00 FL
52	1		*REAR BOOT GLASS MOULDING	Necessary	83.60 FL	*83.60 FL
53	1		*REAR BOOT WIPER ARM	Not Necessary	52.00 FL	*- FL
54	1		*REAR BOOT WIPER BLADE	Not Necessary	43.80 FL	*- FL
55	1		*REAR BOOT WIPER MOTOR	Not Necessary	274.00 FL	*- FL
56	1		*REAR TAIL LAMP R/H	Cut	425.60 FL	*425.60 FL
57	1		*REAR TAIL LAMP PANEL R/H	Not Necessary	185.60 FL	*- FL
58	1		*REAR END PANEL	Dented	358.00 FL	*358.00 FL
59	1		*REAR END PANEL TOP GARNISH	Broken	180.00 FL	*180.00 FL
60	1		*REAR SPARE TYRE PANEL	Not Necessary	947.60 FL	*- FL
61	1		*REAR SPARE TYRE PANEL TOOL TRAY SPONGE	Not Necessary	290.00 FL	*- FL
62	1		*REAR SPARE TYRE PANEL TOP COVER BOARD	Not Necessary	250.00 FL	*- FL
63	1		*REAR FENDER R/H	Repair	985.20 FL	*- FL
64	1		*REAR FENDER INNER GARNISH R/H	Broken	334.90 FL	*334.90 FL
65	2		*REAR FENDER DUST COVER	Not Necessary	81.40 FL	*- FL
66	1		*REAR BUMPER	Dented	856.00 FL	*595.00 FL
67	2		*REAR BUMPER SIDE RETAINER	Broken	50.00 FL	*50.00 FL
68	1		*REAR EXHAUST PIPE	Not Necessary	765.00 FL	*- FL
69	1		*REAR BUMPER CORNER R/H	Cut	41.50 FL	*41.50 FL
70	1		*REAR BUMPER CENTRE MOULDING	Cut	82.00 FL	*82.00 FL
71	1		*REAR FENDER QUARTER GLASS WITH MOULDING R/H	Not Necessary	382.00 FL	*- FL
72	1		*AIRCON SUCTION HOSE	Bent	298.00 FL	*298.00 FL
73	1		*AIRCON DISCHARGE HOSE	Bent	289.00 FL	*289.00 FL
74	1		*FRONT IU BRACKET	Not Necessary	40.00 FS	*- FS
75	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
76	1		*FRONT BUMPER PARKING SENSOR (RH)	Broken	350.00 FS	*150.00 FS
77	1		*FRONT NUMBER PLATE	Broken	45.00 FS	*40.00 FS
78	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*150.00 FS
79	8		*REAR BOOT INNER BOARD CLIPS	Not Necessary	40.00 FS	*- FS
80	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
81	4		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*15.00 FS
82	1		*REAR FENDER INNER GARNISH CLIPS (12 PCS)	Necessary	60.00 FS	*20.00 FS
83	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
84	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
85	1		*BATTERY	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 35,241.30 23,509.80
- List Item Discount on L Items 20.00/20.00% (\$\$) 6,794.26 4,574.96

Total Parts (\$\$) 28,447.04 18,934.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & DIAGNOSTIC FUALT CODE	New	250.00	50.00
2	TUFF KOTE	New	380.00	30.00
3	REMOVE AND REPLACE REAR WINDSCREEN FENDER GLASS	New	180.00	0.00
4	REMOVE AND REPLACE REVERSE SENSOR FRONT +REAR	New	250.00	50.00
5	REMOVE AND REFIX CUSHION SEAT & UPHOLSTERY ETC	New	280.00	0.00
6	REMOVE & REFIX AIRBAG SYSTEM & DIAGNOSTIC SRS WARNING LIGHT	New	450.00	100.00
7	REMOVE & REFIX EXHAUST PIPE	New	150.00	0.00
8	REMOVE & REFIX REVERSING CAMERA	New	150.00	30.00
9	LABOUR CHARGE STRAIGHTEN L/R REAR CHASSIS ,KNOCK DENTS ON REAR WHEEL HOUSE PANEL	New	3,500.00	1,800.00
10	RESPRAY PAINTING	New	2,800.00	1,600.00
Gross Labour Cost (\$\$)			8,390.00	3,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >