

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120207/APA3Q2**Date:** 03/06/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7990000147
Claimant Vehicle No : SNN422B **Insured Vehicle No :** SNN8663U
 Date of Loss: 26/11/2024 Nature of Claim: TP Claim No: 6005487053SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNN422B**
 Make & Model: MERCEDES-BENZ A45 AMG, 2.0 (A) Engine No: 13398080004408
 Reg. Date: 30/05/2014 (Man. Year: 2013) Chassis No: WDD1760522J198090
 Colour: Red Odometer: 2014 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,083.92	3,789.60	7,294.32	65.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	550.00	3,790.00	87.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,423.92	4,339.60	11,084.32	71.86
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	15,423.92	3,450.00	11,973.92	77.63
+ GST 9.00/9.00% (S\$)	1,388.15	310.50	1,077.65	77.63
Nett Amount (S\$)	16,812.07	3,760.50	13,051.57	77.63
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		4,118.75		

INSPECTION

Date of Assignment: 17/12/2024
 Date Inspected: 17/12/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,735.00 FL	*1,409.00 FL
2	1		*REAR BUMPER TOWING COVER	Not Necessary	35.00 FL	*- FL
3	2		*REAR BUMPER SENSOR	Damaged (1 PCS ONLY)	590.00 FL	*295.00 FL
4	4		*REAR BUMPER SENSOR HOLDER	Necessary	260.00 FL	*100.00 FL
5	1		*REAR BUMPER CORNER GRILLE GARNISH RH	Not Necessary	216.30 FL	*- FL
6	1		*REAR BUMPER CORNER INNER GARNISH RH	Not Necessary	165.30 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER	Not Necessary	280.00 FL	*- FL
8	2		*REAR BUMPER BRACKET (CENTER)	Not Necessary	340.00 FL	*- FL
9	1		*REAR BUMPER BRACKET (TOP)	Cracked	365.00 FL	*205.00 FL
10	2		*REAR BUMPER SIDE BRACKET	Not Necessary	190.00 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	760.00 FL	*- FL
12	1		*TAILLAMP	O/S Cracked	1,916.00 FL	*835.00 FL
13	2		*REAR FENDER COWLING	Not Necessary	560.00 FL	*- FL
14	1		*REAR END PANEL	Not Necessary	1,340.00 FL	*- FL
15	1		*REAR BUMPER EXHAUST CHROME PIPE	Not Necessary	496.20 FL	*- FL
16	1		*REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
17	1		*REAR BUMPER DEFFUSER (CARBON FIBER)	Cut	2,500.00 FS	*1,200.00 FS
18	1		*SET REAR FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
19	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
20	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,008.80	4,074.00
- List Item Discount on L Items 10.00/10.00% (S\$)	924.88	284.40
Total Parts (S\$)	11,083.92	3,789.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	250.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	250.00
3	TUFF COAT	New	350.00	0.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	0.00
5	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	580.00	0.00
Gross Labour Cost (\$\$)			4,340.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >