

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120211/KNH3M4**Date:** 06/08/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003607235
Claimant Vehicle No :	SME44T	Insured Vehicle No :	FBW114K
Date of Loss:	07/12/2024	Nature of Claim:	TP
		Claim No:	383996

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME44T		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Engine No:	G4FGJU237310
Reg. Date:	24/08/2018 (Man. Year: 2018)	Chassis No:	KMHD841CMJU728701
Colour:	Metallic Grey	Odometer:	28459 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,592.80	984.80	1,608.00	62.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	950.00	350.00	26.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,892.80	1,934.80	1,958.00	50.30
Approved Total (Overridden) (S\$)		1,550.00		
Nett Amount (S\$)	3,892.80	1,550.00	2,342.80	60.18

INSPECTION

Date of Assignment:	16/12/2024	TROPICAL TECH AUTOMOBILE SERVICES BLK 5032, ANG MO KIO AVENUE 3 #01-303 IND. PARK 2 SINGAPORE 569535
Date Inspected:	20/12/2024 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2025)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME44T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Repair	969.00 FL	*- FL
2	1		*FRONT RH FENDER COWLING	Serviceable	99.00 FL	*- FL
3	1		*FRONT RH DOOR	Bent	1,231.00 FL	*1,231.00 FL
4	1		*FRONT RH DOOR SIDE MIRROR ASSY	Serviceable	776.00 FL	*- FL
5	1		*FRONT RH DOOR WEATHER STRIP	Serviceable	166.00 FL	*- FL
					Sub Total (S\$)	3,241.00 1,231.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	648.20 246.20
					Total Parts (S\$)	2,592.80 984.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND TRANSFER FRONT RH FENDER }	New	600.00	350.00
2	REMOVE AND TRANSFER FRONT RH DOOR NECESSARY ATTACHMENT SPARE PART ITEMS }	New	0.00	0.00
3	REMOVE AND REFIT FRONT RH FENDER, FRONT RH FENDER COWLING, FRONT RH DOOR, FRONT RH DOOR SIDE MIRROR ASSY, FRONT RH DOOR WEATHER STRIP }	New	0.00	0.00
4	PUTTY / PRIMER APPLICATION, SPRAY PAINTING FRONT RH FENDER, FRONT RH DOOR, FRONT RH DOOR SIDE MIRROR	New	700.00	600.00
Gross Labour Cost (\$\$)			1,300.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >