Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Jowyn Tay Mei Ling Date: 04 Aug 2025

Preliminary Advice

Insured Vehicle No : FBW114K

TP Vehicle No : SME44T Accident Date : 07/12/2024

Make : HYUNDAI ELANTRA Assignment Date : 16/12/2024

Date of Inspection : 20/12/2024 Est. Duration of Repair : 4

Inspection At : TROPICAL TECH AUTOMOBILE SERVICES

BLK 5032, ANG MO KIO

AVENUE 3 #01-303 IND. PARK 2

SINGAPORE 569535

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 3,892.80 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 1,934.80 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 1,934.80 |
| | | |
| Lump Sum Repair | :S\$ | 1,550.00 |

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

| () | The vehicle is economical for repair |
|-------|--|
| () | The vehicle is not economical for repair |
| () | Part-by-Part repair |
| (x) | Lump Sum repair |
| | |

(x) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.