



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2502992

INV Date 15/05/2025

Reference CD/LPC24120213/Tua3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 3597Z
Insured Veh. SMH 5510R
Claim No. 24/24/25/VP05/030325
Policy No. Z24VP05034709
Accident Date 13/12/2024
Inspection Date 17/12/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24120213/Tua3q2(N)	
			Date: 15/05/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 5510R	Veh. Inspected	GBJ 3597Z
	Policy No.	Z24VP05034709	Coverage (\$)	0.00
	Claim No.	24/24/25/VP05/030325	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	17/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi canter	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	FEA01BA30097	Colour	WHITE
	Odometer	226201 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	TOYO	6 mm
	L/H Front Tyre	195 R15	TOYO	6 mm
	R/H Rear Tyre	195 R15 (D)	TOYO	6/6 mm
	L/H Rear Tyre	195 R15 (D)	TOYO	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/12/2024	Inspection Date	17/12/2024
	Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 3597Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	TAILLAMP ASSY @\$220.00	CUT	440.00	440.00
2	TAILLAMP BRACKETS @\$250.00	BENT	500.00	400.00
1	TAILBOARD	BENT	4,500.00	2,800.00
3	TAILBOARD HINGE @\$160.00	BENT	320.00	320.00
1	TAILBOARD FUSO STICKER	NECESSARY	110.00	110.00
1	REAR NUMBER PLATE BRACKET	BENT	260.00	260.00
1	AD BLUE CONTAINER	DEFORMED	7,007.00	4,100.00
1	AD BLUE PUMP	BENT	3,800.00	2,400.00
1	AD BLUE SENSOR	NOT NECESSARY	1,600.00	-
1	AD BLUE CONTAINER BRACKET	BENT	980.00	720.00
1	REAR FENDER INNER SHIELD L/H	DEFORMED	210.00	210.00
1	REAR MUD FLAP L/H	NOT NECESSARY	190.00	-
1	REAR EXHAUST	BENT	9,800.00	4,920.00
4	REAR EXHAUST MOUNTING @\$188.00	BENT	752.00	752.00
1	EXHAUST BRACKET	BENT	130.00	130.00
1	EXHAUST CONTROLLER SENSOR	NOT NECESSARY	1,850.00	-
2	EXHAUST HEATER SENSOR @\$1950.00	BENT (1 PCS ONLY)	5,850.00	1,950.00
2	02 SENSOR @\$360.00	BROKEN (1 PCS ONLY)	720.00	360.00
1	EXHAUST CENTER PIPE	BENT	5,600.00	2,500.00
1	REAR SPRING	NOT NECESSARY	1,800.00	-
2	REAR SPRING BRUSH @\$650.00	NOT NECESSARY	1,300.00	-
	LESS 10% DISCOUNT		-4,771.90	-2,237.20
			42,947.10	20,134.80
<u>SPECIAL NETT ITEMS</u>				
1	TAILBOARD 70KMHK STICKER (SN)	NECESSARY	30.00	30.00
1	TAILBOARD 6 PAX STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE (SN)	BENT	45.00	45.00
1	REAR CARRIER ALUMINIUM (SN)	BENT	900.00	600.00
			1,005.00	705.00

Report Ref No. CD/LPC24120213/Tua3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO TRANSFER TAILBOARD .		100.00	60.00
	TO DISMANTLE AND REFIX AND BLUE .		400.00	200.00
	TO DISMANTLE AND REFIX EXHAUST .		200.00	150.00
	TO COMPUTER RESET.		600.00	200.00
	TO CHECK WIRING FUNCTION.		30.00	30.00
	TO APPLY RUSTP PROOFING ON REPLACED /REPAIRED PANEL.		150.00	40.00
	LABOUR CHARGES.		600.00	500.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		600.00	500.00
			2,680.00	1,680.00
GRAND TOTAL			46,632.10	22,519.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				18,000.00

Report Ref No. CD/LPC24120213/Tua3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z





PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 28 of 28)

PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z





PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 3597Z

