

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120215/AMA3Q2**Date:** 03/06/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210009233
Claimant Vehicle No : SMA9011A **Insured Vehicle No :** SMX6925L
 Date of Loss: 15/12/2024 Nature of Claim: TP Claim No: 5536990243SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA9011A**
 Make & Model: TOYOTA VOXY HYBRID, 1.8 V CVT (A) Engine No: 2ZR0B48059
 Reg. Date: 22/06/2018 (Man. Year: 2018) Chassis No: ZWR800317690
 Colour: Black Odometer: 619531 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R16 Rear Tyre Size: 195/65 R16
 Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm
 Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,299.42	4,327.72	14,971.70	77.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,800.00	2,080.00	4,720.00	69.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,099.42	6,407.72	19,691.70	75.45
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	26,099.42	5,100.00	20,999.42	80.46
+ GST 9.00/9.00% (S\$)	2,348.95	459.00	1,889.95	80.46
Nett Amount (S\$)	28,448.37	5,559.00	22,889.37	80.46
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,286.25		
Global Sum Settlement (S\$)		6,280.00		

INSPECTION

Date of Assignment: 16/12/2024
 Date Inspected: 16/12/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE SKIRT LH	Deformed	1,125.30 FL	*1,125.30 FL
2	1		*SLIDING DOOR LH	Dented	1,585.00 FL	*1,585.00 FL
3	1		*SLIDING DOOR STRIP SENSOR LH	Not Necessary	971.50 FL	*- FL
4	1		*SLIDING DOOR OUTER STRIP LH	Not Necessary	1,300.00 FL	*- FL
5	1		*SLIDING DOOR POWER WINDOW MOTOR LH	Not Necessary	487.10 FL	*- FL
6	1		*SLIDING DOOR AUTO SYSTEM MOTOR	Not Necessary	1,993.90 FL	*- FL
7	1		*SET SLIDING DOOR STICKER (BLACK)	Necessary	210.00 FL	*100.00 FL
8	1		*SLIDING DOOR FRONT INNER LOCK LH	Not Necessary	618.10 FL	*- FL
9	1		*SLIDING DOOR INNER TRIM LH	Not Necessary	1,897.40 FL	*- FL
10	1		*SLIDING DOOR FRAME WEATHERSTRIP LH	Not Necessary	577.40 FL	*- FL
11	1		*SLIDING DOOR STEP PANEL LH	Not Necessary	633.70 FL	*- FL
12	1		*SLIDING DOOR STEP PANEL GARNISH LH	Not Necessary	498.80 FL	*- FL
13	1		*SLIDING DOOR WEATHERSTRIP LH	Not Necessary	298.00 FL	*- FL
14	1		*SLIDING DOOR BACK INNER LOCK	Not Necessary	524.30 FL	*- FL
15	1		*SLIDING DOOR LOWER ROLLER LH	Not Necessary	285.00 FL	*- FL
16	1		*SLIDING DOOR LOCK CATCH LH	Not Necessary	78.00 FL	*- FL
17	1		*REAR FENDER LH	Dented	850.00 FL	*850.00 FL
18	1		*REAR FENDER ARCH SEAL LH	Not Necessary	138.10 FL	*- FL
19	1		*REAR FENDER LOWER GUARD LH	Not Necessary	148.10 FL	*- FL
20	1		*REAR FENDER COWLING LH	Not Necessary	158.10 FL	*- FL
21	1		*REAR FENDER INNER SHIELD LH	Not Necessary	218.10 FL	*- FL
22	1		*REAR FENDER GLASS WITH MOULDING	Not Necessary	930.00 FL	*- FL
23	1		*REAR ABS SENSOR LH	Not Necessary	398.00 FL	*- FL
24	1		*REAR SHOCK ABSORBER LH	Not Necessary	395.00 FL	*- FL
25	1		*REAR WHEEL HUP WITH BEARING LH	Not Necessary	995.00 FL	*- FL
26	1		*REAR AXLE	Not Necessary	3,150.00 FL	*- FL
27	1		*REAR BUMPER	Deformed	1,450.00 FL	*1,190.00 FL
28	2		*REAR BUMPER SIDE BRACKET	Not Necessary	156.00 FL	*- FL
29	2		*REAR BUMPER SIDE RETAINER	Not Necessary	156.00 FL	*- FL
30	1		*SET SLIDING DOOR INNER TRIM CLIP RH	Not Necessary	60.00 FS	*- FS
31	1		*REAR FENDER SEALANT LH	Necessary	80.00 FS	*60.00 FS
32	1		*SET REAR FENDER COWLING CLIP LH	Not Necessary	50.00 FS	*- FS
33	1		*REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
34	1		*SET REAR FENDER INNER SHIELD CLIP LH	Not Necessary	30.00 FS	*- FS
35	1		*REAR FENDER GLASS SOLAR FILM	Not Necessary	300.00 FS	*- FS
36	1		*REAR FENDER GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
37	1		*REAR FENDER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR WHEEL TYRE LH	Not Necessary	450.00 FS	*- FS
39	1		*REAR WHEEL RIM LH	Cut	1,200.00 FS	*600.00 FS
40	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
41	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
42	1		*STEP PANEL GARNISH CLIP	Not Necessary	60.00 FS	*- FS
43	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,855.90	5,540.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,556.48	1,212.58
Total Parts (\$\$)	19,299.42	4,327.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,200.00	800.00
2	TO PUTTY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	150.00	30.00
5	REMOVE AND REFIX FUEL TANK	New	120.00	60.00
6	TRANFER FRONT DOOR MECHANISM RH	New	80.00	40.00
7	REMOVE & REINSTALL FRONT WINDOW GLASS RH	New	60.00	40.00
8	REMOVE AND REFIX REAR FENDER QUARTER GLASS RH	New	120.00	0.00
9	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
10	REMOVE AND REFIX REAR UNDERCARRIAGE	New	550.00	0.00
11	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
12	FOUR WHEEL ALIGNMENT	New	120.00	80.00
13	TRANFER SLIDING DOOR MECHANISM RH	New	80.00	60.00
14	REMOVE ,REFIX AND RESET SLIDING DOOR AUTO SYSTEM	New	350.00	0.00
15	REMOVE & REINSTALL REAR WINDOW GLASS	New	60.00	0.00
16	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
17	REMOVE AND REFIX REVERSE SNESOR AND DISTANCE SETTING	New	80.00	50.00
18	RESER ABS LIGHT	New	350.00	0.00
19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			6,800.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >