

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070019/UQH3E2
Date: 31/07/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBE5456K	Insured Vehicle No :	YQ973G
Date of Loss:	28/06/2024	Nature of Claim:	TP
		Claim No:	DMCV2400133H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE5456K		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR EURO V (M)	Engine No:	YD25386744A
Reg. Date:	11/01/2016 (Man. Year: 2015)	Chassis No:	JN1MC2E26Z0005697
Colour:	White	Odometer:	296852 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Toyo 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,789.20	4,941.20	2,848.00	36.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,275.00	1,600.00	675.00	29.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,064.20	6,541.20	3,523.00	35.01
Approved Total (Overridden) (\$\$)		5,200.00		
(\$\$)	10,064.20	5,200.00	4,864.20	48.33
+ GST 9.00/9.00% (\$\$)	905.78	468.00	437.78	48.33
Nett Amount (\$\$)	10,969.98	5,668.00	5,301.98	48.33

INSPECTION

Date of Assignment:	01/07/2024		
Date Inspected:	03/07/2024	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Jul 2024)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR EURO V (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE5456K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
2	1		*REAR END PANEL	Dented/Bent	163.80 FS	*163.80 FS
3	1		*REAR BUMPER PARKING SENSOR	Serviceable	380.00 FS	*- FS
4	1		*REAR BOOT THIRD BRAKE LIGHT	Not Necessary	235.60 FS	*- FS
5	1		*REAR BOOT COVER STICKER 70KM/H	Necessary	28.00 FS	*10.00 FS
6	1		*REAR BOOT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
7	1		*SET REAR END PANEL SEALER	Necessary	80.00 FS	*30.00 FS
8	1		*SET REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
9	1		*REAR BOOT COVER	Dented/Bent	2,021.80 F	*2,021.80 FN
10	1		*REAR BOOT COVER LOGO	Serviceable	72.20 F	*- FN
11	1		*REAR BOOT COVER EMBLEM NV350	Necessary	122.40 F	*122.40 FN
12	1		*REAR BOOT COVER EMBLEM URVAN	Necessary	72.20 F	*72.20 FN
13	1		*REAR BOOT COVER WINDSCEEN	Shattered	1,032.20 F	*991.00 FN
14	1		*REAR BOOT COVER CHROME	Cracked	596.40 F	*449.30 FN
15	1		*REAR BOOT COVER LOCK	Damaged/Jammed	319.30 F	*319.30 FN
16	1		*REAR BOOT COVER LATCH	Not Necessary	56.20 F	*- FN
17	1		*REAR BOOT COVER WEATHER STRIP	Serviceable	149.50 F	*- FN
18	2		*REAR BOOT COVER DAMPER L&R	Not Necessary	480.80 F	*- FN
19	2		*REAR BOOT COVER HINGE L&R	Not Necessary	140.60 F	*- FN
20	1		*REAR BOOT COVER MIRROR	Not fitted	124.90 F	*- FN
21	2		*TAIL LAMP L&R	N/S Not Necessary/O/S Cracked	470.60 F	*235.30 FN
22	1		*REAR BUMPER FASCIA	Dented/Deformed	743.00 F	*743.00 FN
23	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	231.70 F	*231.70 FN
24	6		*REAR BUMPER SIDE RETAINER L&R	Not Necessary	108.00 F	*- FN
					Sub Total (\$)	7,789.20 5,459.80
					- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00 518.60
					Total Parts (\$)	7,789.20 4,941.20

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT, RENEW, KNOCKING & WELDING REAR BOOT COVER, REAR END PANEL, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY	New	880.00	700.00
2	TUFF-KOTE ON DAMAGE PARTS	New	80.00	50.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	1,080.00	680.00
4	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	120.00	120.00
5	REMOVE & INSTALL REAR BUMPER SENSOR	New	80.00	30.00
6	CHECK ALL LIGHTING AFTER REPAIRS	New	35.00	20.00
Gross Labour Cost (S\$)			2,275.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >