
Adjuster: BRYAN TANI**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2025)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1819Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE EMBLEM	Cut	88.00 FL	*88.00 FL
2	1		*RADIATOR GRILLE	Broken	1,409.10 FL	*1,409.10 FL
3	2		*FLAP ASSY ACTIVE AIR UPPER (LH/RH)	Broken	1,649.20 FL	*1,649.20 FL
4	1		*SPEKAR ASSY -VESS	Not Necessary	554.40 FL	*- FL
5	1		*UNIT ASSY SMART CRU (RADAR SENSOR)	Mtg Broken	3,061.40 FL	*2,910.90 FL
6	1		*FLAP ASSY ACTIVE WIRE	Not Necessary	765.30 FL	*- FL
7	1		*FRONT NUMBER PLATE GARNISH	Serviceable	188.00 FL	*- FL
8	1		*FRONT BUMPER COVER	Broken	481.10 FL	*481.10 FL
9	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Serviceable	186.90 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,136.70 FL	*- FL
12	2		*FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH)	Not Necessary	373.00 FL	*- FL
13	1		*FRONT BUMPER TOWING COVER	Not Necessary	29.00 FL	*- FL
14	1		*FRONT BUMPER MOULDING CENTRE UPPER	Serviceable	368.50 FL	*- FL
15	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
16	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
17	1		*FRONT BUMPER LOWER GRILLE	Mtg Cracked	365.30 FL	*365.30 FL
18	1		*FRONT BUMPER LOWER GRILLE MOULDING	Serviceable	127.60 FL	*- FL
19	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
20	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	70.00 FL	*- FL
21	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	56.00 FL	*- FL
22	2		*FRONT BUMPER RETAINER MOUNTIGN (LH/RH)	Not Necessary	130.60 FL	*- FL
23	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
24	2		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	373.80 FL	*- FL
25	2		*FRONT BUMPER AIR DUCT (LH/RH)	Not Necessary	307.60 FL	*- FL
26	1		*DAY LIGHT LH	Not Necessary	642.50 FL	*- FL
27	1		*DAY LIGHT RH	Not Necessary	642.50 FL	*- FL
28	1		*BUZZER ASSY -PIEZO (LH)	Not Necessary	388.00 FL	*- FL
29	1		*HEADLAMP SUPPORT PANEL ASSY	Not Necessary	1,139.30 FL	*- FL
30	2		*HEADLAMP (LH/RH)	Cracked	7,974.60 FL	*4,220.60 FL
31	2		*HORN UNIT (LH/RH)	Not Necessary	145.60 FL	*- FL
32	1		*RADIATOR INVERTER	Not Necessary	884.80 FL	*- FL
33	1		*RADIATOR	Not Necessary	710.50 FL	*- FL
34	1		*RADIATOR FAN BLOWER MOTOR ASSY	Not Necessary	1,459.60 FL	*- FL
35	2		*RADIATOR AIR GUARD (LH/RH)	Not Necessary	152.80 FL	*- FL
36	2		*RADIATOR AIR GUARD UPR (LH/RH)	Not Necessary	255.00 FL	*- FL
37	1		*AIRCON CONDENSER	Bent / Punctured	663.60 FL	*663.60 FL
38	1		*REAR BUMPER	Distorted	459.40 FL	*459.40 FL
39	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
40	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	376.20 FL	*- FL
41	1		*ANTENNA ASSY -SMARTK OUTER	Mtg Broken	689.50 FL	*689.50 FL
42	1		*REAR BUMPER CENTRE MOULDING ASSY	Distorted	451.25 FL	*451.25 FL
43	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Serviceable	47.50 FL	*- FL
44	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
45	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Not Necessary	171.60 FL	*- FL
46	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER UNDER CENTRE	Mtg Broken	123.85 FL	*123.85 FL
48	2		*REAR BUMPER SIDE UNDER (LH/RH)	Not Necessary	246.20 FL	*- FL
49	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
50	1		*REAR BUMPER TOWING COVER	Serviceable	98.80 FL	*- FL
51	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL
52	1		*LICENCE LAMP	Not Necessary	193.53 FL	*- FL
53	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
54	1		*REAR PANEL	Repair	532.00 FL	*- FL
55	1		*ANTENNA ASSY -TRUNK	Not Necessary	689.50 FL	*- FL
56	1		*REAR PANEL GARNISH	Not Necessary	346.80 FL	*- FL
57	1		*REAR NUMBER PLATE }	Cracked	25.00 FS	*45.00 FS
58	1		*REAR NO PLATE TRIM COVER }	Bent	30.00 FS	*- FS
59	1		*COOLANT	Not Necessary	45.00 FS	*- FS
60	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	33,586.63	14,112.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,661.33	2,777.48
Total Parts (\$\$)	26,925.30	11,334.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,200.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX RADIATOR	New	90.00	0.00
7	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
8	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (\$\$)			4,050.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >