

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG24120226/AVH3M4**Date:** 03/03/2025REFERENCE

Insured/Claimant: AW HOCK GUAN (HU FUYUAN) Policy No: 1900090610
Date of Loss: 14/12/2024 Nature of Claim: OD Claim No: 2375862235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA3099Z**
Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK078401
Reg. Date: 23/04/2019 (Man. Year: 2019) Chassis No: WAUZZZF42KA050341
Colour: Grey Odometer: 82580 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$87,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,434.00	2,136.00	27,298.00	92.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,102.00	3,972.00	12,130.00	75.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,536.00	6,108.00	39,428.00	86.59
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	43,936.00	4,508.00	39,428.00	89.74
+ GST 9.00/9.00% (S\$)	3,954.24	405.72	3,548.52	89.74
Nett Amount (S\$)	47,890.24	4,913.72	42,976.52	89.74

INSPECTION

Date of Assignment: 16/12/2024
Date Inspected: 18/12/2024 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,670.00 FS	*2,136.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	648.00 FS	*- FS
3	2	*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	90.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE - CENTER	Not Necessary	245.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	286.00 FS	*- FS
6	1	*FRONT BUMPER AIR GUIDE - RH	Not Necessary	80.00 FS	*- FS
7	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	169.00 FS	*- FS
8	1	*FRONT BUMPER TOP BRACKET	Not Necessary	173.00 FS	*- FS
9	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	156.00 FS	*- FS
10	1	*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,033.00 FS	*- FS
11	2	*FRONT BUMPER REINFORCEMENT BEAM SUPPORT - LH / RH	Not Necessary	73.00 FS	*- FS
12	1	*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	30.00 FS	*- FS
13	1	*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	286.00 FS	*- FS
14	4	*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
15	1	*HEADLIGHT - RH	Not Necessary	9,325.00 FS	*- FS
16	3	*HEADLIGHT COMPENSATING PIECE	Not Necessary	150.00 FS	*- FS
17	1	*LIFT CYLINDER - RH	Not Necessary	252.00 FS	*- FS
18	1	*LIFT CYLINDER BRACKET	Not Necessary	8.00 FS	*- FS
19	1	*LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
20	1	*FRONT FENDER - RH	Repair	918.00 FS	*- FS
21	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	241.00 FS	*- FS
22	1	*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	90.00 FS	*- FS
23	1	*FRONT FENDER BRACKET - RH FRONT	Not Necessary	45.00 FS	*- FS
24	1	*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	72.00 FS	*- FS
25	6	*FRONT FENDER RIVET	Not Necessary	26.00 FS	*- FS
26	1	*FRONT FENDER BRACKET - RH REAR	Not Necessary	67.00 FS	*- FS
27	1	*FRONT FENDER BRACKET - RH UPPER	Not Necessary	42.00 FS	*- FS
28	1	*FRONT FENDER BRACE - RH	Not Necessary	177.00 FS	*- FS
29	1	*FRONT FENDER LEDGE COVER - RH OUTER	Not Necessary	39.00 FS	*- FS
30	1	*FRONT FENDER LEDGE COVER - RH FRONT	Not Necessary	29.00 FS	*- FS
31	1	*FRONT FENDER LEDGE COVER - RH INNER	Not Necessary	76.00 FS	*- FS
32	1	*BONNET	Repair	3,470.00 FS	*- FS
33	3	*BONNET IMPACT PROTECTION - CENTER / RH / LH	Not Necessary	107.00 FS	*- FS
34	1	*BONNET ATTACHMENT PARTS	Not Necessary	460.00 FS	*- FS
35	1	*FRONT PILLAR A/B WITH FRAME MEMBER - RH	Repair	3,320.00 FS	*- FS
36	1	*FRONT WINDOW GUIDE CHROME TRIM STRIP	Not Necessary	320.00 FS	*- FS
37	1	*FRONT WINDSCREEN	Not Necessary	1,618.00 FS	*- FS
38	1	*FRONT RAIN SENSOR GEL FOIL	Not Necessary	140.00 FS	*- FS
39	1	*PRIMER	Not Necessary	27.00 FS	*- FS
40	1	*FRONT DATA TAG	Not Necessary	567.00 FS	*- FS
41	1	*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
42	1	*METAL FILTER POWDER	Not Necessary	280.00 FS	*- FS
43	1	*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
44	1	*STONE CHIP	Not Necessary	180.00 FS	*- FS
45	1	*CAVITY WAX	Not Necessary	140.00 FS	*- FS
46	1	*SUNDRIES	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **29,434.00** **2,136.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
4	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS A-PILLAR. TO REMOVE AND REINSTALL RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,000.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS A-PILLAR	New	3,300.00	2,200.00
7	TO RENEW FRONT WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST	New	680.00	0.00
8	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			16,102.00	3,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >