

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24120228/EVH3E2**Date:** 27/02/2025REFERENCE

Insured/Claimant:	ANDREW ANG LYE WHATT	Policy No:	7220106326-01	
Date of Loss:	21/11/2024	Nature of Claim:	OD	Claim No: 5499850878SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDE3600A</b>		
Make & Model:	AUDI Q5, 2.0 TFSI QU S TRONIC (A)	Engine No:	DGK004229
Reg. Date:	28/02/2022 (Man. Year: 2021)	Chassis No:	WAUZZZF4M2066363
Colour:	Silver	Odometer:	22413 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,164.20	2,916.88	2,247.32	43.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,772.00	3,022.00	2,750.00	47.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,936.20</b>	<b>5,938.88</b>	<b>4,997.32</b>	<b>45.70</b>
<b>- Excess (\$\$)</b>	500.00	500.00	0.00	0.00
<b>(\$\$)</b>	10,436.20	5,438.88	4,997.32	47.88
<b>+ GST 9.00/9.00% (\$\$)</b>	939.26	489.50	449.76	47.88
<b>Nett Amount (\$\$)</b>	<b>11,375.46</b>	<b>5,928.38</b>	<b>5,447.08</b>	<b>47.88</b>

INSPECTION

Date of Assignment:	16/12/2024		
Date Inspected:	23/12/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Dented	1,829.00 FS	*1,463.20 FS
2	1		*FRONT FENDER BRACKET - LH REAR	Not Necessary	22.00 FS	*- FS
3	1		*FRONT FENDER BRACKET - LH CENTER	Not Necessary	22.00 FS	*- FS
4	1		*FRONT FENDER BRACE - LH	Not Necessary	266.00 FS	*- FS
5	1		*FRONT FENDER TOP COVER - LH OUTER	Not Necessary	98.00 FS	*- FS
6	1		*FRONT FENDER TOP COVER - LH	Broken	39.00 FS	*31.04 FS
7	1		*FRONT FENDER TOP COVER - LH FRONT	Broken	50.00 FS	*39.44 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	77.00 FS	*- FS
9	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	318.00 FS	*- FS
10	1		*FRONT WHEEL SPOILER - LH	Not Necessary	200.00 FS	*- FS
11	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	44.00 FS	*- FS
12	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,580.00 FS	*1,264.00 FS
13	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
14	1		*S LINE EMBLEM (NPA)	Necessary	119.20 FS	*119.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)5,164.202,916.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL FRONT BUMPER. TO DISMANTLE AND RENEW LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	750.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	2,600.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (S\$)</b>			<b>5,772.00</b>	<b>3,022.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >