

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24120229/EQH3M4(N)**Date:** 07/01/2025REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZC04741		
Claimant Vehicle No :	SHC1677E	Insured Vehicle No :	GBJ9798X		
Date of Loss:	14/12/2024	Nature of Claim:	TP	Claim No:	M2407333

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1677E	Engine No:	G4LEKU414689
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU191495
Reg. Date:	30/10/2020 (Man. Year: 2019)	Odometer:	368909 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,046.28	7,622.44	5,423.84	41.57
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,960.00	2,200.00	760.00	25.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,018.28	9,834.44	6,183.84	38.60
Approved Total (Overridden) (S\$)		7,850.00		
(S\$)	16,018.28	7,850.00	8,168.28	50.99
+ GST 9.00/9.00% (S\$)	1,441.65	706.50	735.15	50.99
Nett Amount (S\$)	17,459.93	8,556.50	8,903.43	50.99

INSPECTION

Date of Assignment:	16/12/2024 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	16/12/2024 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2025)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1677E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET ASSY	Dented	2,253.80 FL	*2,253.80 FL
2	2		*BONNET HINGE LH/RH	Bent	237.40 FL	*237.40 FL
3	1		*BONNET ABSORBER LH/RH	Not Necessary	35.70 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	127.30 FL	*- FL
5	1		*FRONT FENDER LH	Dented	588.80 FL	*588.80 FL
6	1		*FRONT BUMPER COVER	Broken	481.10 FL	*481.10 FL
7	1		*FRONT BUMPER CENTRE MOULDING	Broken	368.50 FL	*368.50 FL
8	1		*FRONT RADIATOR GRILLE	Not Necessary	1,409.10 FL	*- FL
9	1		*FRONT GRILLE EMBLEM	Not Necessary	48.30 FL	*- FL
10	1		*FRONT RADIATOR TOP COVER	Broken	476.30 FL	*476.30 FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,136.70 FL	*- FL
12	1		*FRONT BUMPER SIDE BRACKET LH/RH	Broken	35.00 FL	*35.00 FL
13	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
14	1		*HEADLAMP SUPPORT PANEL	Broken	949.30 FL	*949.30 FL
15	1		*HEAD LAMP ASSY LH /RH	Broken	2,110.30 FL	*2,110.30 FL
16	1		*FRONT LH DAYLIGHT	Not Necessary	642.50 FL	*- FL
17	1		*FRONT FENDER LH/	Repeated/Not Necessary	588.50 FL	*- FL
18	1		*FRONT FENDER SHIELD LH	Broken	164.70 FL	*164.70 FL
19	1		*FRONT FENDER EMBLEM	Necessary	28.80 FL	*28.80 FL
20	2		*FRONT FENDER RETAINER LH /RH	Not Necessary	82.80 FL	*- FL
21	1		*RADIATOR ASSY	Not Necessary	710.50 FL	*- FL
22	1		*RADIATOR INVERTOR	Not Necessary	884.80 FL	*- FL
23	1		*AIR CON CONDENSER	Not Necessary	663.60 FL	*- FL
24	1		*FRONT HEAD LAMP PANEL	Not Necessary	121.00 FL	*- FL
25	1		*FRONT FENDER APRON PANEL LH	Not Necessary	329.00 FL	*- FL
26	2		*FRONT FENDER ADVERTISEMENT LH/RH	Necessary	200.00 FS	*200.00 FS
Supplementary #1						
27	1		*AIR CLEANER ASSY	Broken	1,336.50 FL	*1,336.50 FL
28	1		*AIR DUCT	Broken	156.80 FL	*156.80 FL
29	1		*FRONT NUMBER PLATE	Broken	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,244.10	9,464.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,197.82	1,841.86
Total Parts (\$\$)	13,046.28	7,622.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,900.00	1,330.00
2	SPARY PAINTING	New	900.00	840.00
3	CHECK WIRING AND LIGHTING	New	60.00	30.00
4	REMOVE/REFIX AIR CON & CHARGE GAS	New	100.00	0.00
Gross Labour Cost (\$\$)			2,960.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >