

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|-----|--|---|-----------------|-------|--------------------------|--|
| | MS FIRST CAPITA | AL INSURANCE LTD | | Ref: | CS/FCI24120230/Evh3e2(N) | |
| | 16 RAFFLES QUA #42-01 HONG LEC 048581 | Y DNG BUILDINGSINGAPORE | | Date: | 07/01/2025 | |
| | ATTN: TEO SWEE | KEONG | | Code: | FCI2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHC 7278J | Veh. Inspected | | SHD 1620M | |
| | Policy No. | D-24101860MFCT | Coverage (\$) | | 0.00 | |
| | Claim No. | D24010978MFCT | Excess (\$) | | 0.00 | |
| | Assign From | TEO SWEE KEONG | Assign Date | | 16/12/2024 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HYUNDAI AE IONIQ | c.c | | 1580 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | |
| | Chassis No. | KMHC851CVKU129663 | Colour | | SILVER | |
| | Odometer | - | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 195/65 R15 | BEARWAY | | 5 mm | |
| | L/H Front Tyre | 195/65 R15 | BEARWAY | | 5 mm | |
| | R/H Rear Tyre | 195/65 R15 | BEARWAY | | 5 mm | |
| | L/H Rear Tyre | 195/65 R15 | BEARWAY | | 5 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND INTERIOR (AIRBAG). | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 14/12/2024 | Inspection Dat | е | 17/12/2024 | |
| | Survey held at | STRIDES PREMIER AUTOMOT | IVE SERVICES PL | _ | | |
| | | 23 CHANGI SOUTH AVE 2 SINGAPORE 486443 | | | | |
| 5a. | Remarks | | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |