

ASS. REC. BY: Taufik

REF: CS/ICS2412.0231/T243

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$325K

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: my key

Vehicle: IN / OUT

Veh No: SMX7077C Yr Regn: 2020, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X7 c.c. 2998

Colour white A/C: Insured / Std / NI / NA

Sp. Reading 34255 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBACW22010965090

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 285/45R21
R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 27/12/24

Survey held at Performance Motors

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

S + RS \$ _____

Photos _____

Others _____

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71966
Date Estimated : 29/11/2024
Prepared By : Yap Mee Key

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Huang ZhiJun
9 Sennett Lane

Singapore 466898

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.
SMX7077C

CHASSIS NO.
WBACW220109C65090

REGN. DATE
17/09/2020

MODEL
X7 xDrive40i

MILEAGE
28368

DESCRIPTION

To replace rear bumper cover painted, make good paintworks, check inner support

VALUE
850 1,275.00

To respray rear bumper and affected areas.

✓ 1,038.00

To check electrical wiring system and lighting at the rear section for proper function.

✓ 177.00

Sundries.

✓ 40.00

Total Labour 1: 2,530.00

DESCRIPTION

RH EXHAUST TAILPIPE TRIM

Check Inner rear support

REAR BUMPER RH PROTECTIVE RUBBER ST

REAR BUMPER COVER PAINTED

QTY	PRIC
1	349.60
1	86.70
1	156.70
1	1,018.55

VALUE
cut 349.60
? 86.70
cut 156.70
cut 1,018.55

Total Parts : 1,611.55

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour 1	:	2,530.00
Parts	:	1,611.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	372.74
Grand Total	:	4,514.29

Acknowledged by Repairer

Signature

Date



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **