



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD

INCOME CENTRESINGAPORE 189557

ATTN: AZHARI AFIDI

Ref: CS/INC24120234/Anh3e2(N)

Date: 03/03/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SND 9408L	Veh. Inspected	SJR 971J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1307869-002	Excess (\$)	0.00
Assign From	AZHARI AFIDI	Assign Date	17/12/2024

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ACCENT	c.c	1368
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHCU41BTKU468481	Colour	GREY
Odometer	102989 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	TOURADOR	6 mm
L/H Front Tyre	175/70 R14	TOURADOR	6 mm
R/H Rear Tyre	175/70 R14	TOURADOR	6 mm
L/H Rear Tyre	175/70 R14	TOURADOR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/12/2024	Inspect Date / Time	17/12/2024 (01:21 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **25 Working Days**