

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 8384J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE (N)	DENTED	1,459.60	1,459.60
1	RIGHT TAILLAMP (N)	BROKEN	289.30	289.30
1	RIGHT SIDEGATE (N)	TO REPAIR SEE LABOUR	1,869.40	-
1	RIGHT SIDEGATE REAR LOCK DEVICE (N)	BENT	285.90	285.90
	LESS 10% DISCOUNT		-	-203.48
			3,904.20	1,831.32
	SPECIAL NETT ITEMS			
1	REAR TAILGATE "70KM/H" STICKER (SN)	NECESSARY	10.00	10.00
1	REAR TAILGATE "13 PAX" STICKER (SN)	NECESSARY	10.00	10.00
1	REAR TAILGATE COMPANY STICKER (SN)	NECESSARY	150.00	150.00
1	REAR TAILGATE INNER ALUMINIUM PLATE (SN)	BENT	250.00	250.00
1	RIGHT SIDEGATE COMPANY STICKER (SN)	NECESSARY	200.00	200.00
2	RIGHT REAR END GUIDE RUBBER @\$30.80 (SN)	O/S TORN	61.60	30.80
			681.60	650.80
	<u>LABOUR</u>			
	CHECK WIRING.		50.00	30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF RIGHT SIDEGATE.		500.00	400.00
	PAINT WORK.		700.00	500.00
			1,250.00	930.00
	GRAND TOTAL		5,835.80	3,412.12

RECOMMENDED COST OF LUMP SUM REPAIRS		2,750.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. CS/INC24120235/Evh3e2(N)

TOTAL FOR SPARE PARTS: \$ 4,585.80 \$ 2,482.12 TOTAL FOR LABOUR: \$ 1,250.00 \$ 930.00 TOTAL REPAIR COST: \$ 5,835.80 \$ 3,412.12

CHEN TSUE YEE

Automotive Assessor

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser