

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD	_	Ref:	CS/INC24120238/Avh3e2(N)	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	26/02/2025	
	ATTN: CHRYLLIS	HAUQ		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKD 3002Z	Veh. Inspected		GBK 1240K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1308312-002	Excess (\$)		0.00	
	Assign From	CHRYLLIS QUAH	Assign Date		17/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV200	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	VM20140013	Colour		GREY	
	Odometer	98418 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14C	KAPSEN		6 mm	
	L/H Front Tyre	175/70 R14C	KAPSEN		6 mm	
	R/H Rear Tyre	175/70 R14C	KAPSEN		6 mm	
	L/H Rear Tyre	175/70 R14C	KAPSEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/12/2024	Inspect Date / 1	Гime	17/12/2024 ( 03:05 PM )	
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD				
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					
	•					