



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 8459T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR - LH (N)	DENTED	1,135.00	1,046.00
1	FRONT DOOR GLASS OUTER MOULDING (N)	NOT NECESSARY	192.00	-
1	FRONT DOOR GLASS RUN CHANNEL (N)	NOT NECESSARY	221.00	-
1	FRONT DOOR GLASS REGULATOR (N)	BENT	385.00	385.00
1	FRONT DOOR INSULATION (N)	TORN	132.00	132.00
1	FRONT DOOR W/STRIP (N)	TORN	189.00	189.00
1	FRONT DOOR INNER TRIM BOARD (N)	BROKEN	782.00	549.00
1	FRONT DOOR CHECKER (N)	NOT NECESSARY	122.00	-
2	FRONT DOOR HINGES @\$135.00 (N)	NOT NECESSARY	270.00	-
1	FRONT FENDER - LH (N)	DENTED	486.00	486.00
1	FRONT FENDER LAMP (N)	CRACKED	89.00	89.00
1	FRONT FENDER INNER SHIELD (N)	CRUSHED	152.00	152.00
1	FRONT FENDER ENCLOSURE (N)	NOT NECESSARY	126.00	-
1	FRONT SPORT WHEEL - LH (N)	NOT NECESSARY	635.00	-
	LESS 10% DISCOUNT		-491.60	-302.80
			4,424.40	2,725.20
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT DOOR BLACK TAPE (SN)	NECESSARY	120.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	60.00	20.00
1	FRONT TYRE (SN)	NOT NECESSARY	200.00	-
			380.00	70.00
<u>LABOUR</u>				
	TO CHECK FRONT ELECTRICAL WIRING.		40.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO TUFF KOTE.		60.00	20.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS.		800.00	600.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS.		800.00	400.00
			1,820.00	1,130.00
GRAND TOTAL			6,624.40	3,925.20

Report Ref No. CS/INC24120239/Evh3e2(N)



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,150.00
---------------------------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS/INC24120239/Evh3e2(N)

TOTAL FOR SPARE PARTS: \$ 4,804.40 \$ 2,795.20
TOTAL FOR LABOUR : \$ 1,820.00 \$ 1,130.00
TOTAL REPAIR COST: \$ 6,624.40 \$ 3,925.20

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.