

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24120242/EVP3M4**Date:** 31/01/2025REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_05
Claimant Vehicle No :	EG388K	Insured Vehicle No :	GBM543H
Date of Loss:	07/12/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EG388K		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030729152
Reg. Date:	10/11/2016 (Man. Year: 2016)	Chassis No:	WDD2050402R216856
Colour:	Silver	Odometer:	6817 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,062.00	8,804.30	3,257.70	27.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	970.00	980.00	50.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,012.00	9,774.30	4,237.70	30.24
Approved Total (Overridden) (S\$)		7,800.00		
Nett Amount (S\$)	14,012.00	7,800.00	6,212.00	44.33

INSPECTION

Date of Assignment:	17/12/2024	
Date Inspected:	18/12/2024 Inspected At:	TWIN WHEEL AUTO TRADING ENTERPRISE (HQ) 38 WOODLANDS ROAD, #03-14 WOODLANDS INDUSTRIAL PARK E1 SINGAPORE 757700
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2025)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EG388K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,917.00 FL	*1,674.00 FL
2	1		*FRONT BUMPER TOP FRAME	Broken	318.00 FL	*318.00 FL
3	1		*FRONT BUMPER INSIDE CENTRE REINFORCEMENT	Not Necessary	120.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	673.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Broken	287.00 FL	*220.00 FL
6	1		*FRONT BUMPER LOWER CHROME	Not Necessary	330.00 FL	*- FL
7	1		*FRONT BONNET	Dented	2,592.00 FL	*2,240.00 FL
8	1		*FRONT BONNET LOCK	Not Necessary	348.00 FL	*- FL
9	1		*FRONT BONNET BAGS	Necessary	96.00 FL	*96.00 FL
10	1		*FRONT HEAD LAMP	Broken	4,427.00 FL	*3,879.00 FL
11	1		*FRONT HEAD LAMP PANEL	Not Necessary	180.00 FL	*- FL
12	1		*SET FRONT GRILLE	Broken	980.00 FL	*800.00 FL
13	2		*FRONT BONNET HINGS	Not Necessary	312.00 FL	*- FL
14	1		*SET FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
15	2		*FRONT BUMPER SENSOR	Shorted	680.00 FS	*500.00 FS
					Sub Total (\$\$)	
					13,320.00	9,727.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	
					1,258.00	922.70
					Total Parts (\$\$)	
					12,062.00	8,804.30

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO SPRAY PAINT	New	800.00	440.00
2	LABOUR TO PANEL BEATING	New	800.00	450.00
3	RESET OF HEAD LAMP LIGHT	New	350.00	80.00
Gross Labour Cost (\$\$)			1,950.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >