



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
ATTN: ERIC WOO

INV No. AC2508195

INV Date 28/11/2025

Reference CD/LPC24120243/Tma3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJN 6199D
Insured Veh. GBG 38G
Claim No. 24/24/24/VC05/030310
Policy No. Z24VC05022216-003
Accident Date 11/12/2024
Inspection Date 18/12/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: ERIC WOO			Ref: CD/LPC24120243/Tma3q2(N) Date: 28/11/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 38G	Veh. Inspected	SJN 6199D
	Policy No.	Z24VC05022216-003	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030310	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	18/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO XC90	c.c	1969
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	YV1LFL1TCN1809687	Colour	GREY
	Odometer	74815 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/45 R20	PIRELLI	6 mm
	L/H Front Tyre	275/45 R20	PIRELLI	6 mm
	R/H Rear Tyre	275/45 R20	PIRELLI	6 mm
	L/H Rear Tyre	275/45 R20	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/12/2024	Inspection Date	18/12/2024
	Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 6199D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	V001161824/*D* PRIME (SN)	NECESSARY	48.20	43.38
1	*D* GLASS CLEANER H (SN)	NECESSARY	102.50	92.25
2	*D* WINDSCREEN SEALA (SN)	NECESSARY	340.60	306.54
1	V032244967/WINDSCREEN (SN)	NECESSARY	1,995.00	1,795.50
1	V031455985/TAILGATE (SN)	BENT	4,228.50	3,805.65
1	EMBLEM 'VOLVO' REAR (SN)	NECESSARY	135.90	122.31
1	EMBLEM 'XC 90' XC90 (SN)	NECESSARY	135.90	122.31
1	EMBLEM B5 SPA (SN)	NECESSARY	135.90	122.31
1	EMBLEM AWD XC90 16 (SN)	NECESSARY	114.60	103.14
1	BUMPER COVER REAR KI (SN)	DEFORMED	3,042.90	2,738.61
1	BRACKET BUMPER REAR (SN)	NOT NECESSARY	94.90	-
1	BRACKET BUMPER REAR (SN)	NOT NECESSARY	94.90	-
1	BUMPER TRIM BLACK LH (SN)	NOT NECESSARY	164.10	-
1	BUMPER TRIM BLACK RH (SN)	NOT NECESSARY	164.10	-
1	TOW COVER REAR XC90 (SN)	NOT NECESSARY	67.30	-
1	BUMPER REFLECTOR LH (SN)	NOT NECESSARY	97.60	-
1	BUMPER REFLECTOR RH (SN)	NOT NECESSARY	97.60	-
1	PROTECTING PLATE REA (SN)	DEFORMED	470.30	423.27
1	PROTECTING PLATE REA (SN)	DEFORMED	391.30	352.17
1	SPOILER BRACKET LH X (SN)	NOT NECESSARY	43.60	-
1	SPOILER BRACKET RH X (SN)	NOT NECESSARY	43.60	-
1	BUMPER INSTAILLING MT (SN)	NECESSARY	101.40	91.26
10	BUMPER CLIP SPA (SN)	NECESSARY	77.00	69.30
10	BLIND RIVET 4.0*21 P (SN)	NECESSARY	55.00	49.50
10	BUMPER CLIP 8X8 ,5 (SN)	NECESSARY	62.00	55.80
10	SPRING NUT GREEN (SN)	NECESSARY	52.00	46.80
10	EXPANDING NUT XC40 1 (SN)	NECESSARY	79.00	71.10
1	V031698776/BUMPER RA (SN) (ADDITIONAL)	BENT	1,084.95	1,084.95
1	V032149879/TAILGATE (SN) (ADDITIONAL)	DISTORTED	477.63	477.63
1	TAILGATE BOARD XC90 (SN) (ADDITIONAL)	DAMAGED	261.54	261.54

Report Ref No. CD/LPC24120243/Tma3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DECAL (SN) (ADDITIONAL)	NECESSARY	3.87	3.87
			14,263.69	12,239.19
	LABOUR			
	TO REPAIR REAR END PANEL . (ADDITIONAL)		900.00	900.00
	TO PUTTY SPRAY PAINT REAR END PANEL ,REAR BEAM. (ADDITIONAL)		1,275.00	1,275.00
	TO REPLACE REAR BOOT LID ,REAR BUMPER ,REAR LOWER SPOILER ,ETC .		2,700.00	1,800.00
	TO PUTTY SPRAY PAINT ON REAR BOOT LID ,REAR BUMPER,REAR LOWER SPOILER ,ETC.		3,400.00	2,550.00
	TO TRANSFER REAR BOOT LID ,PART .		250.00	250.00
	TO REPLACE REAR WINDSCREEN.		900.00	900.00
	TO INSTALL REAR WINDSCREEN FIL.		320.00	320.00
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.	NOT NECESSARY	60.00	-
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		570.00	570.00
			10,375.00	8,565.00
GRAND TOTAL			24,638.69	20,804.19
RECOMMENDED COST OF REPAIRS				20,804.19

Report Ref No. CD/LPC24120243/Tma3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 15)

PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 15)

PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 14 of 15)

PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D



PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SJN 6199D

