

ASS. REC. BY: TaughtREF: CD/LPC24120243/Tm93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$200k *

IDAC Accident Report _____ Consistent?: Yes or No

GIA / PR Seer: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Richmond Vehicle: IN / OUTVeh No: SJN6199D Yr Regn: 2021/12Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo XC90 c.c. 1969Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 74815 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV/LF/LTCN1809687Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / SR / STD A/Rim orTyre Size: F: 275/45R20R: - -BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 18/12/24Survey held at WearnesDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.B./C: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS: _____

Photos _____

Others _____

TOTAL

SERVICE ESTIMATE

96279 - C00001
Mr Ung Chuong Hing
257 Belgravia Drive

Singapore
Singapore 804307

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Ung Chuong Hing

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 12/12/2024

WIP No. . : 33589

Veh.In/Out: 12/12/2024

*Tel.No. . : Mobile: 92381018

Reg.No. . : SJN6199D

Reg.date . : 17/12/2021

Mileage .. : 0

Chassis No: YV1LFL1TCN1809687

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID,REAR BUMPER,REAR LOWER SPOILER,ETC	0	2700.00	0		2,700.00	S 1800
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR LOWER SPOILER,ETC	0	3400.00	0		3,400.00	S 2550
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00	S ✓
802	TO REPLACE REAR WINDSCREEN	0	900.00	0		900.00	S ✓
89994	TO INSTALL REAR WINDSCREEN FIL	0	320.00	0		320.00	S ✓
R06	TO INSTALL REAR NUMBER PLATE	0	60.00	0		60.00	SX
INCLUDE HOLDER							
287	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	0	570.00	0		570.00	S ✓
	V001161824/*D* PRIME	1.0 EA	48.20			48.20	S rec ✓
	D GLASS CLEANER H	1.0 EA	102.50			102.50	S rec ✓
	D WINDSCREEN SEALA	2.0 EA	170.30			340.60	S rec ✓
	V032244967/WINDSCREE	1.0 EA	1995.00			1,995.00	S rec ✓

Tanjum 97495749/62563561
WP' 18/12/2015
p/p Resurvey before paint
Tanjum clikauto.com.
7days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

96279 - C00001
Mr Ung Chuong Hing
257 Belgravia Drive

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Singapore
Singapore 804307

Inv.No. . : B&P 0 Page 2
Inv.date. : 12/12/2024
WIP No. . : 33589
Veh.In/Out: 12/12/2024
*Tel.No. . : Mobile: 92381018
Reg.No. . : SJN6199D
Reg.date . : 17/12/2021
Mileage .. : 0
Chassis No: YV1LFL1TCN1809687

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Ung Chuong Hing

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	V031455985/TAILGATE	1.0 EA	4228.50			4,228.50	S bt ✓
	EMBLEM 'VOLVO' REAR	1.0 EA	135.90			135.90	S nel ✓
	EMBLEM 'XC 90' XC90	1.0 EA	135.90			135.90	S nel ✓
	EMBLEM 'B5' SPA	1.0 EA	114.60			114.60	S nel ✓
	Emblem 'AWD' XC90 16	1.0 EA	114.60			114.60	S nel ✓
	BUMPER COVER REAR KI	1.0 EA	3042.90			3,042.90	S de ✓
	BRACKET BUMPER REAR	1.0 EA	94.90			94.90	S ?
	BRACKET BUMPER REAR	1.0 EA	94.90			94.90	S ?
	BUMPER TRIM BLACK LH	1.0 EA	164.10			164.10	S ?
	BUMPER TRIM BLACK RH	1.0 EA	164.10			164.10	S ?
	TOW COVER REAR XC90	1.0 EA	67.30			67.30	S ?
	BUMPER REFLECTOR LH	1.0 EA	97.60			97.60	S X
	BUMPER REFLECTOR RH	1.0 EA	97.60			97.60	S X
	PROTECTING PLATE REA	1.0 EA	470.30			470.30	S de ✓
	PROTECTING PLATE REA	1.0 EA	391.30			391.30	S de ✓
	SPOILER BRACKET LH X	1.0 EA	43.60			43.60	S ?
	SPOILER BRACKET RH X	1.0 EA	43.60			43.60	S ?

SERVICE ESTIMATE

96279 - C00001	SL: SERVICE SALES - PC	GST Reg.No:M28920628X
Mr Ung Chuong Hing		Inv.No. . : B&P 0 Page 3
257 Belgravia Drive		Inv.date. : 12/12/2024
Singapore		WIP No. . : 33589
Singapore 804307		Veh.In/Out: 12/12/2024
		*Tel.No. . : Mobile: 92381018
		Reg.No. . : SJN6199D
Closed by : Richmond Ho		Reg.date .: 17/12/2021
Svc Consultant :		Mileage ... : 0
Remarks : Mr Ung Chuong Hing		Chassis No: YV1LFL1TCN1809687

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER INSTALLING MT	1.0 EA	101.40			101.40	S <i>rec</i> ✓
	BUMPER CLIP SPA	10.0 EA	7.70			77.00	S <i>rec</i> ✓
	BLIND RIVET 4.0*21 P	10.0 EA	5.50			55.00	S <i>rec</i> ✓
	BUMPER CLIP 8x8,5	10.0 EA	6.20			62.00	S <i>rec</i> ✓
	SPRING NUT GREEN	10.0 EA	5.20			52.00	S <i>rec</i> ✓
	EXPANDING NUT XC40 1	10.0 EA	7.90			79.00	S <i>rec</i> ✓

		Gross Total.	20,614.40
Labour Total	8,200.00	Net.....	20,614.40
Parts Total	12,414.40	GST @ 9.0%	1,855.30
Package Total	0.00	Total.....	22,469.70
		Paid.....	0.00
		Please Pay..	22,469.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate