

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24120246/ENP3E2**Date:** 24/12/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAB00156		
Claimant Vehicle No :	SHA1863U	Insured Vehicle No :	SMT1781M		
Date of Loss:	14/12/2024	Nature of Claim:	TP	Claim No:	M2407356

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1863U	Engine No:	G4LEKU298657
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVKU164726
Reg. Date:	17/07/2019 (Man. Year: 2019)	Odometer:	630575 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,587.84	0.00	2,587.84	100.00
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,420.00	970.00	450.00	31.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,019.84	982.00	3,037.84	75.57
+ GST 9.00/9.00% (\$\$)	361.79	88.38	273.41	75.57
Nett Amount (\$\$)	4,381.63	1,070.38	3,311.25	75.57

INSPECTION

Date of Assignment:	17/12/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	17/12/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Dec 2024)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1863U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	481.10 FL	*- FL
2	1		*FRONT BUMPER BRACKET LH	Not Necessary	55.80 FL	*- FL
3	1		*FRONT FENDER LH	Repair	558.80 FL	*- FL
4	1		*FRONT FENDER EMBLEM LH	Not Necessary	28.80 FL	*- FL
5	1		*HEAD LAMP LH	Not Necessary	2,110.30 FL	*- FL
					Sub Total (\$\$)	3,234.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	646.96
					Total Parts (\$\$)	2,587.84

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	760.00	380.00
2	SPARY PAINTING	New	600.00	560.00
3	CHECK LIGHTING	New	60.00	30.00
Gross Labour Cost (\$)			1,420.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >