

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070022/DMA3Q2
Date: 17/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0007538_02
Claimant Vehicle No : SHD6667X Insured Vehicle No : SMV1898A
Date of Loss: 30/06/2024 Nature of Claim: TP Claim No: MPC2024D0008114

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6667X
Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (AUTO) (2WD) (A) Engine No: 2ZR2R16797
Reg. Date: 29/04/2022 (Man. Year: 2022) Chassis No: JTDKB3FU903096594
Colour: Blue Odometer: 370046 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,530.00	4,186.67	20,343.33	82.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	1,380.00	3,040.00	68.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,950.00	5,566.67	23,383.33	80.77
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	28,950.00	4,450.00	24,500.00	84.63
+ GST 9.00/9.00% (S\$)	2,605.50	400.50	2,205.00	84.63
Nett Amount (S\$)	31,555.50	4,850.50	26,705.00	84.63
+ Car Rental (7.0 x S\$119.68/day) (S\$)		837.76		
+ Loss of Earnings (7.0 x S\$40.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		6,075.51		
Global Sum Settlement (S\$)		6,050.00		

INSPECTION

Date of Assignment: 02/07/2024
Date Inspected: 02/07/2024 Inspected At: BIFROST AUTO PTE LTD - LOYANG (HQ)
59 Loyang Drive Level 4 Room 7
Singapore 508969
Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2024)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (AUTO)(2WD) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD6667X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Dented / Bent	1,577.24 FL	*1,577.24 FL
2	1		*REAR TRUNK LID LOCK	Serviceable	641.06 FL	*- FL
3	1		*REAR TRUNK LID LOCK COVER	Not Necessary	129.80 FL	*- FL
4	1		*REAR TRUNK LID LOCK SWITCH	Not Necessary	468.90 FL	*- FL
5	1		*REAR TRUNK LID COVER TRIM BOARD	Not Necessary	303.10 FL	*- FL
6	1		*REAR TRUNK LID RUBBER	Deformed	511.28 FL	*511.28 FL
7	1		*REAR TRUNK LID LAMP G5	Not Necessary	891.52 FL	*- FL
8	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Not Necessary	2,197.58 FL	*- FL
9	1		*BOARD ASSY ,BACK DOOR TRIM	Not Necessary	356.16 FL	*- FL
10	1		*GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	Repair	1,845.58 FL	*- FL
11	1		*REAR TRUNK LID LOGO (PRIUS)	Serviceable	85.12 FL	*- FL
12	1		*REAR TRUNK LID LOGO (HYBRID)	Serviceable	73.36 FL	*- FL
13	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Serviceable	74.06 FL	*- FL
14	1		*THIRD BRAKE LIGHT	Not Necessary	552.58 FL	*- FL
15	1		*REAR TRUNK LID STRIKER	Not Necessary	138.18 FL	*- FL
16	2		*REAR TRUNK LID HINGE (LH/RH)	Not Necessary	530.60 FL	*- FL
17	2		*REAR TRUNK LID ABSORBER (LH/RH)	Not Necessary	805.00 FL	*- FL
18	2		*REAR TRUNK LID ABSORBER BRACKET (LH/RH)	Not Necessary	358.12 FL	*- FL
19	2		*REAR TRUNK LID STOPPER (LH/RH)	Not Necessary	237.44 FL	*- FL
20	1		*SPOILER SUB-ASSY ,REAR	Not Necessary	1,335.18 FL	*- FL
21	1		*REAR BUMPER	Dented	642.04 FL	*642.04 FL
22	1		*REAR BUMPER REINFORCEMENT	Cracked	446.32 FL	*446.32 FL
23	1		*REAR BUMPER UNDER COVER	Not Necessary	773.64 FL	*- FL
24	2		*REAR BUMPER SIDE RETAINER	Not Necessary	315.56 FL	*- FL
25	1		*REAR BUMPER UNDER CENTRE COVER	Not Necessary	773.64 FL	*- FL
26	1		*REAR BUMPER TOWING COVER	Not Necessary	115.78 FL	*- FL
27	1		*REAR BUMPER CLIPS	Necessary	30.80 FL	*30.80 FL
28	2		*REAR BUMPER SIDE CLIP	Not Necessary	70.00 FL	*- FL
29	1		*ARM SUB-ASSY ,REAR BUMPER RH	Not Necessary	195.44 FL	*- FL
30	1		*REAR BUMPER UNDER SIDE COVER (RH)	Not Necessary	324.80 FL	*- FL
31	1		*RETAINER ,REAR BUMPER SIDE RH	Not Necessary	132.72 FL	*- FL
32	2		*RETAINER ,REAR BUMPER UPPER SIDE (LH/RH)	Not Necessary	85.96 FL	*- FL
33	1		*RETAINER ,REAR BUMPER SIDE LH	Not Necessary	132.72 FL	*- FL
34	1		*REAR BUMPER UNDER SIDE COVER (LH)	Not Necessary	324.80 FL	*- FL
35	1		*ARM SUB-ASSY ,REAR BUMPER LH	Not Necessary	195.44 FL	*- FL
36	1		*REAR BUMPER LOWER COVER GARNISH G5	Dented	963.63 FL	*963.63 FL
37	2		*TAIL LAMP ASSY (UPPER) G5	Not Necessary	1,885.80 FL	*- FL
38	2		*TAIL LAMP ASSY (LOWER) G5	Not Necessary	1,721.16 FL	*- FL
39	2		*TAIL LAMP QUARTER PANEL	Not Necessary	604.80 FL	*- FL
40	1		*REAR END PANEL GARNISH COVER	Not Necessary	138.90 FL	*- FL
41	2		*TAIL LAMP SIDE COVER	Not Necessary	716.80 FL	*- FL
42	1		*REAR END PANEL	Dented	842.94 FL	*842.94 FL
43	1		*REAR END PANEL GARNISH	Not Necessary	294.80 FL	*- FL
44	1		*REAR SPARE TYRE PANEL	Not Necessary	960.80 FL	*- FL
45	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Serviceable	668.90 FL	*- FL
46	1		*REAR FIBER TOOL BOX TRIM	Not Necessary	557.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SPARE TYRE LOCK NUT	Not Necessary	123.76 FL	*- FL
48	1		*REAR WINDSCREEN GLASS W/ MOULDING	Not Necessary	2,489.62 FL	*- FL
49	1		*REAR WINDSCREEN SEALANT	Not Necessary	64.40 FL	*- FL
50	1		*REAR TRUNK LOWER W/S MOULDING	Not Necessary	180.00 FS	*- FS
51	1		*REAR LOWER W/S SEALANT	Necessary	46.00 FS	*46.00 FS
52	1		*REAR NO PLATE WIHT TRIM COVER	Not Necessary	140.00 FS	*- FS
53	1		*REAR TRUNK LID APPS STICKER	Necessary	56.00 FS	*56.00 FS
54	1		*REAR TRUNK LID COMFORT & TEL NO STICKER	Necessary	84.00 FS	*84.00 FS
55	1		*REAR BUMPER REVERSE SENSOR	Damaged	189.98 FS	*189.98 FS
56	1		*REAR BUMPER RUBBER MAT	Deformed	70.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	30,471.01	5,440.23
- List Item Discount on L Items 20.00/25.00% (S\$)	5,941.01	1,253.56
Total Parts (S\$)	24,530.00	4,186.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING CHARGE	New	1,400.00	600.00
3	WIRING CHARGE	New	100.00	20.00
4	TUFF KOTE	New	100.00	20.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	60.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			4,420.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >