

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-36/37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

ESTIMATE COST OF REPAIR

Date: 17-Dec-24

Estimate no. 1564

Plate No. FBU9218X

Model. ADV160

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	REAR SIDE COVER RED / CH	\$ 200.00	/	
2	PILLION SIDE COVERSET SILVER LEFT /	\$ BR 150.00	/	
3	PILLION BOTTOM SIDE COVERSET SILVER /	\$ BR 180.00	/	
4	LEFT SIDE FOOTREST COVER BLACK /	\$ CH 220.00	/	
5	FRONT BOTTOM COVERSET BLACK /	\$ BR 200.00	/	
6	FRONT MIDDLE COVER SET BLACK /	\$ BR 180.00	/	
7	MAIN STAND / BT	\$ 120.00	/	
8	SIDE STAND / BT	\$ 85.00	/	
9	LEFT MIDDLE INNERCOVER ?	\$ CRA 180.00	/	
10	FRONT LEFT SIDE COVERSET RED /	\$ BR 250.00	/	
11	LEFT SIDE SIGNAL FRONT / BR	\$ 150.00	115 /	
12	LEFT SIDE SIGNAL FRONT / CH (PH)	\$ 150.00	115 /	
13	HANDLE BAR / BT	\$ 220.00	200 /	
14	LEVER SET / CH	\$ 150.00	/	
15	BAR LEVERGUARD / CH	\$ 120.00	/	
16	LEFT SIDE MIRROR / CH	\$ 220.00	140 /	
17	LEFT SIDE PILLION BAR / CH	\$ 160.00	/	
18	CVT CASING SILVER / CH	\$ 280.00	260 /	
19	CVT COVER BALCK / CH	\$ 120.00	/	
20	PRESS BODY (labour)	\$ 450.00	200 (labour)	
21	FORKSET ? x nn	\$ 800.00	/	
22	FOOTREST RUBBER / CH	\$ 95.00	/	
23	WINGS CASING / MS	\$ 85.00	60 /	
24	LABOUR	\$ 800.00	300 (labour)	

Steve (LKK)

18/12/24, 11.00 AM

in R

2/5

by AI

3 days

Logo \$45 / SCR

Tail light mudguard \$85 / CRA

Less 10%	\$	556.50
	\$	5,565.00
Sub Total :	\$	5,008.50
GST 9%	\$	450.77
Total:	\$	5,459.27

*Estimate given are base on visible damages ONLY before dismantling of the vehic

This is computer generated no signature is required.

3430

-10%

3,087 + 500 (labour) = 3587.00

L/S - 2,869.6

= 2850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: