



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: JASON TEA		Ref: CS/FCI24120249/Evp3m4(N) Date: 08/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8238D	Veh. Inspected	FBU 9218X
Policy No.	D-24101860MFCT	Coverage (\$)	0.00
Claim No.	D24010876MFCT	Excess (\$)	0.00
Assign From	SWEE KEONG TEO	Assign Date	17/12/2024
2. Vehicle Particulars & Condition			
Make & Model	HONDA ADV160	c.c	157
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	MH1KFB217NK008448	Colour	RED
Odometer	21051 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70-14	DUNLOP	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/60-13	DUNLOP	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/12/2024	Inspection Date	18/12/2024
Survey held at	SYNERGY @ KAKI BUKIT 23 #01-18 KAKI BUKIT ROAD 4		
Repairer	ERZAT LEE MOTOR TRADING PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	