



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8123J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	300.00	300.00
1	SET FRONT BUMPER CLIP	NECESSARY	30.00	30.00
2	FRONT BUMPER RETAINER LH / RH	* CHECK	100.00	-
2	FRONT BUMPER TOWING COVER LH / RH	SERVICEABLE	30.00	-
1	FRONT REINFORCEMENT	TO REPAIR SEE LABOUR	220.00	-
1	FRONT REINFORCEMENT SPONGE	SERVICEABLE	60.00	-
1	FRONT RADIATOR GRILL	CRACKED	400.00	400.00
2	FRONT RADIATOR GRILL COVER LH / RH	SERVICEABLE	50.00	-
1	FRONT EMBLEM	MISSING	120.00	120.00
2	HEADLAMP LH / RH	MTG CRACKED	4,800.00	4,800.00
2	HEADLAMP GARNISH LH / RH	SERVICEABLE	80.00	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	320.00	-
1	FRONT BONNET SEAL	SERVICEABLE	40.00	-
2	FRONT BONNET HINGE LH / RH	TO REPAIR SEE LABOUR	100.00	-
1	SET FRONT BONNET INSULATOR CLIP	NOT NECESSARY	30.00	-
1	FRONT BONNET MOULDING - CHROME	MTG CRACKED	180.00	180.00
1	FRONT BONNET LOCK MECHANISM	TO REPAIR SEE LABOUR	50.00	-
2	FRONT FENDER LH / RH	TO REPAIR SEE LABOUR	900.00	-
2	FRONT FENDER INNER LINER LH / RH	SERVICEABLE	130.00	-
2	SET FENDER INNER LINER CLIP	NOT NECESSARY	60.00	-
2	FRONT FENDER BRACKET LH / RH	TO REPAIR SEE LABOUR	90.00	-
1	FRONT RADIATOR SUPPORT TOP	TO REPAIR SEE LABOUR	240.00	-
1	FRONT RADIATOR SUPPORT BOTTOM	TO REPAIR SEE LABOUR	120.00	-
2	RADIATOR AIR GUIDE LH / RH	SERVICEABLE	100.00	-
	COST PLUS 10%		855.00	583.00
			9,405.00	6,413.00

Report Ref No. CS/SMO24120250/Knp3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	50.00	-
1	FRONT PARKING SENSORS (SN)	SERVICEABLE	200.00	-
			250.00	-
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING FRONT FRAME MEMBERS. INCLUSIVE OF THE REPAIR OF FRONT REINFORCEMENT, FRONT BONNET, FRONT BONNET HINGE LH / RH, FRONT BONNET LOCK MECHANISM, FRONT FENDER LH / RH, FRONT FENDER BRACKET LH / RH, FRONT RADIATOR SUPPORT TOP AND FRONT RADIATOR SUPPORT BOTTOM.		1,000.00	500.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,200.00	400.00
	TO INSTALL NEW PARKING SENSOR.		180.00	50.00
	TO CALIBRATE PARKING SENSOR AND FORWARD COLLISION SENSORS AFTER REPAIR.	NOT NECESSARY	150.00	-
			2,530.00	950.00
GRAND TOTAL			12,185.00	7,363.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$110.00 NETT)				7,363.00

Report Ref No. CS/SMO24120250/Knp3e2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.