



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBH 5434H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NO-PLATE	NOT NECESSARY	\$30.00	\$0.00
1	REAR NO-PLATE BASE	NOT NECESSARY	\$25.00	\$0.00
1	REAR FENDER (LH)	TO REPAIR SEE LABOUR	\$2,150.00	\$0.00
			\$2,205.00	\$0.00

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE (N)	DENTED	\$1,177.00	\$1,177.00
2	REAR TAILGATE LOCK (RH,LH) @\$195.00 (N)	NOT NECESSARY	\$390.00	\$0.00
1	REAR TAILGATE OUTER HANDLE (N)	NOT NECESSARY	\$165.00	\$0.00
2	REAR TAILGATE HINGE (RH,LH) @\$135.00 (N)	NOT NECESSARY	\$270.00	\$0.00
2	REAR TAILGATE SUPPORT RUBBER (RH,LH) @\$147.00 (N)	NOT NECESSARY	\$294.00	\$0.00
1	REAR 3RD BRAKE LIGHT (N)	BROKEN	\$197.00	\$197.00
1	REAR MITSUBISHI EMBLEM (N)	NECESSARY	\$47.00	\$47.00
1	REAR DHD EMBLEM (N)	NECESSARY	\$60.00	\$60.00
2	REAR L200 EMBLEM (N)	NECESSARY	\$38.00	\$38.00
1	REAR SPORTERO EMBLEM (N)	NECESSARY	\$70.00	\$70.00
1	REAR NO PLATE PANEL (N)	NOT NECESSARY	\$985.00	\$0.00
1	REAR TAIL LAMP (RH,LH) @\$330.00 (N)	BROKEN	\$660.00	\$660.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$224.90)
			\$4,353.00	\$2,024.10

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION		\$60.00	\$30.00
	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM		\$100.00	\$80.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC. INCLUSIVE OF THE REPAIR OF REAR FENDER (LH)		\$1,200.00	\$800.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS		\$900.00	\$800.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA		\$80.00	\$30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REFIX FENDER TRIM, GARNISH & ETCS...	NOT NECESSARY	\$100.00	\$0.00
			\$2,440.00	\$1,740.00
GRAND TOTAL			\$8,998.00	\$3,764.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,000.00
Report Ref No: CS/LIP24120259/Enh3e2				

MARKET VALUE: \$39,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,825.00=NETT VALUE: \$33,175.00

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.