

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	R	ef:	CS/INC24120262/Enh3m4(N)	
	75 BRAS BASAH FINCOME CENTRE	Da	ate:	03/01/2025	
	ATTN: CHARLOTT	E CHEW	C	ode:	INC
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLE 1921S	Veh. Inspected		YQ 7493D
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1308403-002	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		18/12/2024
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI CANTER	c.c		2998
	Engine No.	HIDDEN	Year of Reg.		2022
	Chassis No.	FEB21EA35781	Colour		WHITE
	Odometer	105330 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195R15C	BRIDGESTONE		5 mm
	L/H Front Tyre	195R15C	BRIDGESTONE		5 mm
	R/H Rear Tyre	195R15C	BRIDGESTONE		5 mm
	L/H Rear Tyre	195R15C	BRIDGESTONE		5 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
	DAWAGEG GEE DI	LIAILO.			
5.	General Information				
	Accident Date	14/12/2024	Inspect Date / Tir	ne	18/12/2024 (10:40 AM)
	Survey held at	CARSMITH PTE LTD	<u> </u>		
		8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
	1				