

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJX 1550C

REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR BUMPER LH PARKING SENSOR	SCRATCHED	\$345.30	\$345.30	
	LESS 5.00% DISCOUNT		(\$17.27)	(\$17.26)	
			\$328.03	328.04	

Labour						
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
TO REPAIR DAMAGES		\$250.00	\$180.00			
TO SPRAY PAINTING		\$400.00	\$300.00			
		\$650.00	\$480.00			
GRAND TOTAL	\$978.03	808.04				
RECOMMENDED COST OF REPAIRS			\$808.04			
Report Ref No: CS/SP	F24120264/Kvp3e2					

NOTES: THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$808.04-\$978.03

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.