



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: CHRYLLIS QUAH

Ref: CS/INC24120265/Aqh3e2(N)

Date: 24/03/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMR 8649C	Veh. Inspected	SJZ 5525P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1307449-002	Excess (\$)	0.00
Assign From	CHRYLLIS QUAH	Assign Date	18/12/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA CRX	c.c	1590
Engine No.	HIDDEN	Year of Reg.	1991
Chassis No.	JHMED93700S310032	Colour	BLACK
Odometer	423434 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S, FRONT PORTION
AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/12/2024	Inspect Date / Time	18/12/2024 (11:58 AM)
Survey held at	N-51 AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **13 Working Days**