

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120268/Avh3e2(N)	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	28/02/2025	
	ATTN: HELENA TA	۸N		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBT 5194L	Veh. Inspected	t	SKN 4200J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1308434-002	Excess (\$)		0.00	
	Assign From	HELENA TAN	Assign Date		18/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ESTIMA	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	ACR500165489	Colour		SILVER	
	Odometer	154137 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/45 R18	PIRELLI		6 mm	
	L/H Front Tyre	235/45 R18	PIRELLI		6 mm	
	R/H Rear Tyre	235/45 R18	PIRELLI		6 mm	
	L/H Rear Tyre	235/45 R18	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/12/2024	Inspect Date /	Time	18/12/2024 (11:30 AM)	
	Survey held at	RYDER AUTO PTE LTD				
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					