

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24120271/DVP3E2  
**Date:** 08/01/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003943557
<b>Claimant Vehicle No :</b>	SMV4579B	<b>Insured Vehicle No :</b>	GBC3867G
Date of Loss:	17/12/2024	Nature of Claim:	TP
		Claim No:	385566

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMV4579B</b>	Engine No:	PE31517780
Make & Model:	MAZDA CX-30, 2.0 CLASSIC (A)	Chassis No:	JM6DM2W7AL0100308
Reg. Date:	30/09/2020 (Man. Year: 2019)	Odometer:	59423 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,574.60	2,148.40	12,426.20	85.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	930.00	1,370.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,874.60</b>	<b>3,078.40</b>	<b>13,796.20</b>	<b>81.76</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (\$\$)</b>	<b>16,874.60</b>	<b>2,400.00</b>	<b>14,474.60</b>	<b>85.78</b>

INSPECTION

Date of Assignment:	19/12/2024	Alfred Auto Services & Supplies (HQ) Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2 Singapore 569538
Date Inspected:	18/12/2024 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2025)
<b>Parts:</b>	M1-SUV	MAZDA CX-30 2.0 CLASSIC (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMV4579B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Repair	2,038.00 F	*- FL
2	1		*REAR BOOT LOCK	Not Necessary	498.00 F	*- FL
3	1		*REAR BOOT CX-30 EMBLEM	Not Necessary	210.00 F	*- FL
4	1		*REAR SKYACTIV G EMBLEM	Not Necessary	199.00 F	*- FL
5	1		*REAR BOOT WEATHER SLIP	Serviceable	450.00 F	*- FL
6	1		*REAR BUMPER	Distorted	1,830.00 F	*1,373.00 FL
7	1		*REAR BUMPER BEAM	Broken	460.00 F	*460.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Bent	1,280.00 F	*746.00 FL
9	1		*REAR BUMPER SIDE RETAINER	Not Necessary	298.00 F	*- FL
10	1		*REAR BUMPER SPONGE	Not fitted	485.00 F	*- FL
11	2		*REAR BUMPER REFLECTOR	Not Necessary	410.00 F	*- FL
12	1		*REAR BUMPER TOWING COVER	N/S Distorted/O/S NotNecessary	138.00 F	*69.00 FL
13	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
14	2		*REAR EXHAUST CHROME	Not Necessary	980.00 F	*- FL
15	1		*REAR EXHAUST	Not Necessary	2,980.00 F	*- FL
16	1		*REAR END PANEL	Repair	998.60 F	*- FL
17	4		*REAR PARKING SENSOR	Serviceable	1,240.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,574.60</b>	<b>2,678.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	529.60
<b>Total Parts (\$\$)</b>	<b>14,574.60</b>	<b>2,148.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT WIRE, AND CHECK WIRING	New	120.00	30.00
2	TO REMOVE & REFIT INTERIOR GARNISH, SIDEBBOARD	New	180.00	0.00
3	TO KNOCKING, STRAIGHTENING, REPAIR & RENEW ALL ACCIDENT AFFECTED AREA	New	1,000.00	500.00
4	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA	New	1,000.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>2,300.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >