

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 1330071301C CS1 Reg. No. 13 30071301C					
	Affiliated to Federation Internationale Des Experts En Automobile				
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI24120273/Eqp3m4(N)	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 03/01/2025	
	ATTN: MONICA C	HUNG	Cod	le: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMV 6656Z	Veh. Inspected	GBK 7065K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10033521/MC	Excess (\$)	0.00	
	Assign From	LAN BOON CHIN	Assign Date	18/12/2024	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	JTFHT02PX09990291	Colour	WHITE	
	Odometer	102287 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195R15C	BRIDGESTONE	5 mm	
	L/H Front Tyre	195R15C	BRIDGESTONE	5 mm	
	R/H Rear Tyre	195R15C	BRIDGESTONE	5 mm	
	L/H Rear Tyre	195R15C	BRIDGESTONE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/12/2024	Inspection Date	18/12/2024	
	Survey held at	CARSMITH PTE LTD			
		8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: