

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SHD 6507A

Policy No. _____

Claims No. D24011034MFCT


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$36K

IDAC Accident Report _____ Consistent?: Yes or No

GIA / PR Seem _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 98044 Yr Regn: 2016/08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Tayyib + Harrier c.c. 1986

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 214129 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 75460 0073.534

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/12/2024 D.O.I. 18/12/24

Survey held at Jin Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/2/25	LS \$6500 confirmed with Jouis (Red 4491.51, 40%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS \$ _____

Photos _____

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

JinAuto

Tel: 62898126 Fax: 62870590

Email: jin@jinauto.com.sg

Company Reg No: 200704370C , GST Reg No : 200704370C

M/S COMFORT DELGRO

16-12-24

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA HARRIER - SLE9804U

DOA: 14/12/2024

S/N	QTY	DESCRIPTION	AMOUNT
1	1 PC	TAILGATE	\$ 2175.40 <i>bt</i>
2	1 PC	TAILGATE LOCK	\$ 647.10 <i>?</i>
3	1 PC	TAILGATE EMBLEM	\$ 79.60 <i>ucl</i>
4	1 PC	TAILGATE "HARRIER" EMBLEM	\$ 84.90 <i>ucl</i>
5	1 PC	TAILGATE WEATHERSTRIP RUBBER	\$ 515.40 <i>?</i>
6	1 PC	REAR BUMPER	\$ 2336.30 <i>de</i>
7	1 PC	REAR BUMPER LOWER	\$ 649.40 <i>de</i>
8	1 PC	REAR BUMPER LOWER RED REFLECTOR - LH	\$ 91.80 <i>cnr</i>
9	1 PC	REAR BUMPER SIDE RETAINER - LH	\$ 156.40 <i>?</i>
10	1 PC	REAR BUMPER SIDE RETAINER - RH	\$ 156.40 <i>X</i>
11	1 PC	END PANEL	\$ 1252.20 <i>?</i>
12	1 PC	END PANEL TOP GARNISH	\$ 501.20 <i>?</i>
13	1 PC	REAR TAIL LAMP - LH	\$ 736.40 <i>X</i>
14	1 PC	SPARE TYRE PANEL	\$ REPAIR
			\$ 9382.50
		Less 25%	\$ -2345.62
			\$ 7036.88
15	1 SET	REVERSE SENSOR	\$ 280.00 <i>200mm</i>
16		SEALANT & GUM	100.00 <i>60</i>
17	1 SET	BUMPER CLIPS	\$ 70.00 <i>40</i>
18		SPRAY PAINTING	\$ 950.00 <i>750</i>
19		LABOUR CHARGE	\$ 1100.00 <i>800</i>
20		WIRING	\$ 50.00 <i>30</i>
21		LABOUR FOR REVERSE SENSOR	\$ 80.00 <i>30</i>
22		TUFF KOTE	\$ 80.00 <i>30</i>
23		LABOUR FOR REAR WINDSCREEN	\$ 120.00 <i>✓</i>
24		REMOVE AND REFIX CARPET ,GARNISHES	\$ 80.00 <i>60</i>
			<u>9946.88</u>

Tanjiu 97495749 / 62563561
'wp' 18/12/24 @ 430 PM

tanjiu@khanh.com
c/s Resurvey after repair
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Co.

Acknowledged by Repairer

Signature:

Date: